

**REMONUMENTATION**

MAR 19 1997

**COMMISSION**

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in KEWEENAW - REMON Located in: \_\_\_\_\_  
(County)

Corner Code # \_\_\_\_\_

REGISTER'S OFFICE }  
County of Keweenaw } SS  
Received for Record, the 8<sup>th</sup>  
day of November A.D. 1996  
at 11:00 o'clock A.M., and Recorded  
in Liber. 1 of LCP  
on page 144  
Robert Rosenberger, Deputy  
Register of Deeds

Register of Deeds Stamp & File Number

- |                                      |   |            |   |            |            |
|--------------------------------------|---|------------|---|------------|------------|
| 1. Public Land Survey                | T | <u>57N</u> | R | <u>32W</u> | <u>F-9</u> |
|                                      | T |            | R |            |            |
|                                      | T |            | R |            |            |
|                                      | T |            | R |            |            |
| 2. Property Controlling in Section   | S |            | T |            | R          |
|                                      | S |            | T |            | R          |
| 3. Miscellaneous Property in Section | S |            | T |            | R          |
|                                      | S |            | T |            | R          |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

|    |    |    |    |    |    |    |   |   |   |   |   |   |
|----|----|----|----|----|----|----|---|---|---|---|---|---|
| A  | B  | C  | D  | E  | F  | G  | H | I | J | K | L | M |
| 2  | 6  | 5  | 4  | 3  | 2  |    |   |   |   |   |   |   |
| 3  |    |    |    |    |    |    |   |   |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |   |   |   |   |   |   |
| 5  |    |    |    |    |    |    |   |   |   |   |   |   |
| 6  | 18 | 17 | 16 | 15 | 14 | 13 |   |   |   |   |   |   |
| 7  |    |    |    |    |    |    |   |   |   |   |   |   |
| 8  | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |   |   |
| 9  |    |    |    |    |    |    |   |   |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |   |   |   |   |   |   |
| 11 |    |    |    |    |    |    |   |   |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |   |   |   |   |   |   |
| 13 |    |    |    |    |    |    |   |   |   |   |   |   |

I, R. W. CRAMPTON, in a field survey on JUNE 20, 1985 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

F-9 N 1/4 CORNER SECTION 28-SET POST- CEDAR 12 N24W, FIR 3 S10E 20.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

F-9 N 1/4 CORNER SECTION 28-2" IRON PIPE IN CONCRETE (FND), COR FALLS 31.37'  
EAST OF GLO NOTES



**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

F-9 THE 2" IP WITH 4" BRASS CAP WAS WITNESSED WITH SURVEY TAG NAILED TO:  
12" CEDAR TREE N76W 47.25', 5" SPRUCE TREE S74E 11.25',  
5" MAPLE TREE S7E 16.1', 14" TWIN W BIRCH TREE S31W 25.63'.

Ratified by Peer Group  
In accordance with P.A. 345  
Co. Rep. James M. Scholtz  
10/15/96

Signed by Robert W. Crampton  
Surveyor's Michigan License No. 24591

Date OCTOBER 1, 1996