SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

or corners in				REGISTER'S OFFICE SS
Keweenaw	Located In:	Corner Code#		County of Keweenaw J 24h
(County)	 -			
I. Public Land Survey	у Т <u>57</u> R <u>3</u>	3 M-7	į	day of Delwher A.D. 19 99 at 1:00 o'clock P.M., and Recorded
1.1 gone pario carro	T <u>57</u> R <u>3</u>	3 M-8 V	-	in Liber of UR
· ·	<u>TR</u>		·	on page 214
n Droporty Controllin	TR_ na S TR_		<u> </u>	on page Twils on thought
2. Property Controlling in Section	S TR_			V
3. Miscellaneous	S TR		. [The state of the same of the Number
Property in Sec.	S IR	<u> </u>	٠	Register of Deeds Stamp & File Number
4. Lot No , \	Recorded Plat			ABCDEFGHIJKLM
5. Private Claims				2 5 4 5 1 2
	•			3
		9/28 19 99 do h	ereby state that und	ler 4 7 8 9 10 10 11 12
I, James M. Part	ini, in a field survey on Michigan P.A. of 1970, the corner	points mentioned in lines 1	and 2 above were	In 5
	ons and fules therefore as legalited tof the Interior, Bureau of Land Mai sphioned in lines 3, 4 and 5 above w			
Board of Land Surveyor	s or by a Decree of a Coult of	Law; established, re-estat	olisned, monument	8 19 20 21 22 23 24
recovered, found as expre	1			9
	2 comers, all in the same town	and range, may be recor	dea	10 30 29 28 27 26 25
on this certific	ate.			
				12 31 32 33 34 35 36
	ią.			13
A Danadakan af orio	inal monument and accessorie	s and/or subsequent re	storation:	
(M_7) NF Cor	spinal monument and accessore Sec 24, T57N-R33W, V	NOON POST SET PJ	11000	rt in 1845.
U.S. Bearing	Trace III SI	JUAN STEN	L,	
	30" He	emlock N59°W ugar S40°E	18 1ks 37 1ks	
Samuel W. Hil		40000	14 14 0	
Subdivision I	57N-R33W 12" Corner section 24.	57N-R33W, wood	post set fo	or quarter section corner by Austin
Burt DS in 18	45. U.S. Bearing Tr	rees.		
DUI C DO 111 20	→ 10" Ma	apie 320 W	18 1ks	
	12" P	ine N38°E	18 1ks	
B. Description of co	rner evidence found and/or me	ethod applied in restoring n records ind	g or reestablishing Tcate∵an Tr	g corner: on pipe set in concrete. Found pipe in concrete 6" below grade
(M-/) Calume	Walt Kline in 1953.	Found and acc	epted iron	pipe in concrete 6" below grade
(Disturbed).	i i	_		hatuan saction carners North
(M-8) Re-esta	ablished & corner by	single proport	ionate meas	ure between section corners North
and South.				
•				Ratified by Peer Group In accordance with P.A. 345
				(1. Mull. 1/1
				Co. Rep. fine Mall
	r f			Date
_	onument for corner and access	orios established to Der	netuate locating t	the position of the corner:
C. Description of m	onument for corner and access	" brass cap marl	ked "Keween	the position of the corner: aw Co., Remonumentation Point" 8"
helow grade	at pase of disturbe	d pipe.		
14" Red Pi	ne N48'E 45.40'			
6" Aspen	S13°E 56.18' e S46°W 37.68'			AF BE MICHIO
Utility pol- Utility pol	100 LOS COS			
(M-8))Set 1"	e N11 W 122.00 'x36" iron pipe /w 4	" brass cap mark	ked " Keweer	naw Co., Remoramenta Mes Will A. Lo-
cated at cor	rner of clear cut.			78°E 48.76' * LAND **
10" Aspen	NO5°W 11.34'	18" White	e Birch N	SURVEYOR
8" Red Ma	aple N50°E 19.57'	. 1		No. 153
1 1	aple N55°E 42.75	melie	Date	12/7/9 32340
Signed by	32340			CANDS
Surveyor's Michigan	I License No.			