## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in				County of Keweenaw SS
Keweenaw County	Located in:		Corner Code #	Received for Record, the
1. Public Land Survey	T58N T58N T	R	A13 C13	at 11:00 o'clock A: M., and Recorded in Liber 1 of LCR
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T S T S T	R R R R		on page 197  Maily Ulaquest  Register of Deeds  Register of Deeds  Register of Deeds
I, Steven C. Hein, in a field surve of P.A. 74, Michigan P.A. of 19 conformance with regulations a instructions of the United States decree of a Court of Law and /or in conformance with the rules of of Law; established, re-established	70, the corner points and rules therefore as Department of the Inthat the corner point the Michigan Board and monumented, rec	mentioned is required in terior, Bures is mentioned of Land Survivovered, foun	in lines 1 and 2 above were the current manual of su au of Land Management or d in lines 3, 4 and 5 above we reyors or by a Decree of a C	A B C D E F G H I J K L  1
A. Description of original mo-	nument and acces	sories and/	or subsequent restoration	on:
A13: SW Corner Section Townships 57 &	n 31: From origir 58 N. between F	ial notes: Ranges 30	North on East side of 9 & 31 West; Y. Birch 1	Sec. 1, T57N, R31W; 80.00 Set post Corner to 14 N68E 15 lks.; Sugar 10 S53W 12 lks. No

C13: Corner between Sections 31 & 32: From original notes: East on South side of Sec. 31, T58N, R30W: 76.75 Set post Corner to Secs. 31 & 32; Birch 12 N19E 36 lks.; B. Oak 14 N26W 22 lks.. No evidence of original corner or

accessories found.

Ratified by Peer Group

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

evidence of original corner or accessories found.

Date

A13: SW Corner Section 31: Found 1" square pin in concrete as recorded J. I. Haataja, P.S. 19833 in Liber 1 of L.C.R.C., Page 58. Witnesses of said record: 10" Maple N65°E 8.69'; 10" Maple N26°E 16.71'; 10" Maple N75°W 26.15'; 5" Ironwood S38°W 24.17'

C13: Corner between Sections 31 & 32: Having found the recorded Southwest and Southeast Corners of the Township, all the Section corners between were set on a true parallel of latitude established by using the secant method. Positions fit well with found evidence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

A13: Accepted 1" Square pin in concrete,

No Brass Cap set

Witnesses(As recorded):

10" Maple N65°E 8.69'

10" Maple N26°E 16.71'

10" Maple N75°W 26.15' 5" Ironwood S38°W 24.17' C13: Set 4" Brass Cap stamped for

corner on 1" pipe, 7" A.G.

Witnesses:

12" H. Maple N67°E 17.25'

6" H. Maple S42°E 16.67' 8" H. Maple S61°W 10.60'

6" H, Maple N65°W 22.91'



Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983 REVISED OCT., 1995