BUFFVEY & PENCHURATETON

FEB 1 8 1994

. Recorded Plat

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE

	マンツがいる Filing Require	ement of Act 74, Mich. P./	4.1970 P T 2 7 7 1
For comers in	•	•	Z < < ~
Kalamazoo	Located In:	Corner Code ##	P. 21 D
(County)			
Public Land Survey	т <u>1 S</u> R <u>9 W</u>	C-2	ANDR R
	T R		STI 8
	T R	· · · · · · · · · · · · · · · · · · ·	ER CO AA
	T R		(S Ro
2. Property Controlling	S T R		URER 1 PC1088
in Section	S T R		LIBER 1 PG1UOO
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		riogister of books statisf at the statistics.

1. Robert E. Snell , in a field survey on December 14 $do\ hereby\ certify\ that\ under\ requirements\ of\ P.A.\ 74, Michigan\ P.A.\ of\ 1970, the\ corner\ points\ mentioned$ in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

Description of original monument and accessories and/or subsequent restoration: East 1/4 Post established by United States Government Survey in 1826

> Wh. Oak 24" South 11°-E 60 Lks (39.6') 9" 20 Lks (13.2') North 59°-W Wh. Oak

1882-Ed Strong, County Surveyor-Reset stake and stones from one good U.S. Witness 1883-F. Hodgeman, County Surveyor-Found stake bored 3'. Put stone in bottom and 2' Earthen Post over.

Wh. Oak 24" North 118 1/4 Lk (78.05') Wh. Oak 24" North 72 1/2-E 44 Lk (29.04')

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner with accessories not recovered. Found 1/2" x 6" rerod over solid clay tile with "X" on top with accessories from previous survey and Kalamazoo County Surveyor records.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 12/16/93

10

11

12

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

East 1/4 Post Section 6, T. 1 S., R. 9 W., Ratified by Kalamazoo County Remonumentation Program Peer Group on December 16, 1993. Found 1/2" x 6" rerod over solid clay tile as called for in previous Wilkins & Wheaton Engineering survey and 1883 Remonumentation by F. Hodgeman and is accepted as a careful and faithful perpetuation of the original corners position. Removed 1/2" x 6" iron rod and placed monument sleeve over solid clay tile with $1/2" \times 6"$ iron rod over.

8" W. Cherry PK Nail in North side North 75°-E 13.92 42" W. Cherry South 88°-W 59.951 PK Nail in North side 8" W. Cherry North 37°-30' West 9.5' PK Nail in West side South 08°-30'-E 32.44' PK Nail in West side 8" Elm

Signed by

Date

Surveyor's Michigan License No. 9734