## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE - MOHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

'94 MAR 17 PM 3 39

For	corners in R	OSS	TWP.					,	_							
KAL	AMAZOO (County)		<del></del>	Located In:	Corner Code ##				2	<del>77.</del>	su?		- Car	سعو	/	
1.	Public Land Su	rvey	r	T <u>1 SR 9 W</u> T R	G_8				CLi	ERF	(-RI	V EGIS	e TE	R		
				T R T R				LIBE	F		1	PG.	1	20	)	
2.	Property Contro	olling		T R												
•	in Section			TR												
3.	Miscellaneous			<u>T</u> <u>R</u>		Regi	ster	of E	)eed	ls S	tamp	) & F	ile l	Num	ber	
	Property in Sec	;.	s _	TR												
4.	Lot No.	\	Recorde	d Plat				R	a	n	E F	G	H I	l .f	ĸ	LM
							Ë	Ť	Ť	ĒΠ	<u>-</u>	Ť	ΪĪ		Ť	
							2	- 6	+-	5− I	<b>4</b>	+	3-	-2	+	- <u>†</u> —
				,			3 -	┿	+			+	┼╌┤		+	+
					•		4	- 7	-	8—	<u> </u>		10—	-11	+	-12-
IA1	len H.McM	lache	ana in a fi	eld survey onJan	uary 31 , 19 94	,	5	_				-	$\bot$	<b>-</b>	_	_
dot	nereby certify that	undern	equiremen	its of P.A. 74, Michigan P.A.	of 1970, the corner points menti-	oned	6	 -1 <b>8</b> —	1	7_	.—16–	_	15	14	_	13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the							7	$\perp$		$\sqcup$				$\sqcup$	$\downarrow$	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							8	_19					22	_23		24
abo	ve were in confort	тапсе ч	with the ru	les of the Michigan Board o	of Land Surveyors or by a Decre	e of a	او	Ĩ	•	Ĭ	ιÌ	L	Ī	ΙÏ		_Ī
Court of Law; established, re-established, monumented, re-monumented, recovered, found as							10	Ţ	Τ.						T	Ţ
	ressed below:						11	-30— 	2	9	28- 	7	2/—	26 		25 
NOTE: Not more than 4 corners, all ill the same town and range, may be recorded								╈	+		$\Box$	_			$\top$	
	on this ce	rtificat	e.				12	-3'1— I	-3	(2 I	33-	-+-:	34	-35 I	-	36
	Description of	oriolos	l monum	ont and accessories on	d/or subsequent restoration	ı-	13 L						Ļ	<del></del>		
Α.		_														
	<u>1880's</u> -	· F.	Hodge	eman C.S. Plac	ed Clay Tile pos	t auri	ng									
		of:	ficial	Township Rem	onumentation.											

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile at surface

AMAZOO COUNTY MONUMENTATION PEER GROUP 3-3-94



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Place Standard Sleeve over existing Clay Tile, accessories:

3" Dia. Steel pipe (10' high) Nail & Tab in Southwest face

Nail & Tab in Southwest face

Nail & Tab in South face

Northwest corner of Consumers Power Co. Electric Transmission Tower

NORTH 0.4'

8" Oak N. 22 deg. W. 52.45'

10" Oak N. 70 deg. W. 110.20'

10" Pine S. 80 deg. W. 149.32'

N.75 deg. E. 74.7'

Signed by Surveyor's Michigan License No.