4. Lot No. _ 5. Private Claims

1 PG 1122 LIBER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE	HIGAN
COUNTY	S. S. AMAZO
RECEIVED E	OR RECORD

For corners in ROSS TWP.	Filing Require	ment of Act /4, Mich. P.A. 19	'94 MAR 17 PM 3 39
KALAMAZOO (County)	Located In:	Corner Code ##	\bigcirc
Public Land Survey	T <u>1 S</u> R <u>9 W</u> T R T R T R	<u>K-4</u>	CLERK-REGISTER
2. Property Controlling S _ in Section S _	T R T R		×
3. Miscellaneous S Property in Sec. S	T R		Register of Deeds Stamp & File Number

l. Randy B. Ligman in a field survey on <u>January 24</u>, 19 <u>94</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

___ , Recorded Plat _

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

3

Description of original monument and accessories and/or subsequent restoration:

1883 - F. Hodgeman C.S. Placed Clay Tile post during official Township Remonumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile in marsh at intersection of North-South and East-West fence line remnants



OF MICH RANDY B LIGMAN LAND SURVEYOR No. 28413

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Standard Sleeve over existing Clay Tile and placed "T" fence post next to sleeve, accessories:

Found 1½" OD galvanized pipe

Nail & Tab in East face

Nail & Tab in South face

Nail & Tab in East face

Nail & Tab in South face

South 8.2'

7" Elm N. 27 deg. E. 12.91'

10" Double Maple EAST 17.98'

6" Elm SOUTH 21.79'

12" Maple WEST 33.16'

Surveyor's Michigan License No. 2841

VED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983