SURVEY & REMONUMENTATION

1	1
2	

APR 27 1995

STATE OF MICHIGAN AUNTY OF KALAMAZOO

nm o EE

COMMISSION

PK Nail in West Side

PK Nail in East Side

PK Nail in South Side 17" Oak PK Nail in Southeast Side 24" Oak

LAND CORNER RECORDATION CERTIFICATE Ciling Domisinomant of Sat 74 Mint DA 4070

COUN	11	VΓ	NAL	AMAZOU
RECE	ΙVΕ	D	FOR	RECORD

For	corners	in	riing i	vedniteme	ent of Act /4,	MICH. P.,	A. 1970	1941	ULU b	rii o	3 3 .	
<u>Ka</u>	lamazo		Located In:		Corner Code =	#			١	E Property	~/	
A1 1.	amo To	County) Wnship and Survey	T <u>1 S</u> R _ T R _ T R _		E-11				CLERK	- REGISTI	ER	
3.	Property in Section Miscellar Property	on neous	T R _ S T R _ S T R _ S T R _				Re		BER Deeds S	1 PG1		
				-		L .						
		laims, Rec	orded Plat				Ŋ	2 6 3	3 C D	E F G H	J K	L M
.	Robert	E. Snell	n a field survey on	May 2		O.A.		4 - 7	8			-12
in lin curre Mana abov Cour	nes 1 and ent manua agement of re were in rt of Law essed bel	ify that under require 2 above were in could of survey instruction by a decree of a Coconformance with the cestablished, revelow:	ements of P.A. 74, Michiconformance with regular ons of the United States ourt of Law and/or that the rules of the Michigan established, monument error, all in the same to	gan P.A. of 19; tions and rule s Department ne corner poir Board of Lan ed, re-monu	70, the corner poi es therefore as r t of the Interior, B nts mentioned in I d Surveyors or b mented, recover	nts mention equired in sureau of L ines 3, 4 as y a Decree red, found	the and nd 5 of a	5 6 18 7 8 19 10 30	20 29 29 32	28 27 28 33 34	23 26 35	-13 -24 -25 -36
	Dan awimbi							13				
	Descripti 1829:		nument and accessor (, U.S. Governm				er to	Secti	ons 28.	, 29, 32	& 33.	1.
		Wh. Oak	7" F	or Cornei	r Post							M_{κ}
	1870:	F. Hodgeman, Marked	, County Survey	or; Sect	ion Corner	tree s	tandi	ng.	RA	71FIED AZOO NUMENT NUMENT	COUNT AXION	En.
		Y. Oak Wh. Oak	14" 12"		80° East 84° East	60 82	Lks Lks	BYK	EMON	TIFIED AZONT IUM CRIT	AL V	
	Descripti 1964:	Acro Enginee (found stone previous sur	ence found and/or mering; Set 3/8" e, from previous evey) measured set Northeast Co 2643.00).	iron roo s survey) from East	d for North), and Nort t 1/4 Post	east C heast to Nor	orner. 1/8 Co theast	corner: Cornorner crner	er set (found Corner	from Ea stone, (1321.4	st 1/4 from 5) and	Post
	1994:	3/8" x 18" i	ron rd from pre	evious wi	itness.							•
		1987; Wilkin	ns & Wheaton Wi	tness	24" Oak 18" Oak				20.78' 50.15'			
		1977; G. Smi	th Witness	,	12" Oak 6" Oak			dest dest	30.21 45.631			
r. .	laenrinti.	an of monument fo	or corner and access	orige actab	liched to norma	stuato los	ating +5	a nociti	on of the	corpor:		
O. 1		Southwest Co Remonumentat previous wit as a careful	or comer and access orner Section 28 cion Program Pec ness (see "B" a and faithful a "Harrison monur	B, T. 1 S er Group above) as re-estab	S., R. 12 W on July 21 s re-establ lishment of	Rat , 1994 ished the p	ified . Four by Act	by th nd 3/8 ro Eng	e Kalar " x 18' ineerin	mazoo Co 'Iron r ng and a	erod fr ccepted	om

Note all nails were existing in trees. _ Date _ gned by _ 9734 eyor's Michigan License No. _

North 58° East 45.88'

North 14° East 30.22' South 52° East 50.12' South 28° West 21.8'

12" Oak

15" Oak 17" Oak

CL of "F" Ave North 6.5'