## SURVEY & REMONUMENTATION

JUL 2 3 1997 COMMISSION LIBER 2PAGE 119 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Alamo Township For corners in Kalamazoo Corner Code # Located In: T 1S. R 12W. 1. Public Land Survey R 2. Property Controlling \_\_T \_\_\_\_R\_ 1200 in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section \_, Recorded Plat\_ 4. Lot No. Private Claims \_ ı, <u>Allen H. McMachen</u>, in a field survey on <u>January 10</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1954 - Plat of "Cross Acres" is 1974 - R.L. Sauers, R.L.S., L. 1829 - Robert Clark, Jr., D.S., 1, Surveys, Pg. 533 "Drill

Set quarter Section post, Cherry 22" N. 24° E. 15 lks., W. Oak 22" S. 58° W. 21 lks. 1872 - E. Strong, C.S., "Stone 18" x 8" x 8" "

recorded L. 20, Pg. 6 and shows W.1/4 cor. Section 3 at 1111.27' West of centerline 6th Street

Hole in stone" 40" Box Elder East 25.94', 30" Cherry West 22.38', 6" Cherry S. 40° E. 27.95'

--

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found stone with drill hole 0.5' below grade. Stone measures 10" x 10" x 24" and directly under East and West fence. Measured East  $\pm 1111'$  to centerline 6th Street. Stone matches 1974 witness to box elder.

> RATIFIED ( BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 2-27-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found stone with drill hole is accepted as a careful and faithful perpetuation of the position of the original corner. Moved stone to West and placed Harrison monument at position of drill hole, Accessories:

"PK" Nail in West side 8" Twin Cherry N. 25° E. 27.00'

"PK" Nail in North side 40" Box Elder East 26.21'

"PK" Nail in Southwest side 10" Maple S. 25° E. 7.30'

"PK" Nail in South side 10" Elm West 29.40'

MICH ALL EN H McMACHEN **PROFESSIONAL** SURVEYOR No. 16935 PROFESSIONAL Date

Signed by Surveyor's Michigan License No.

REVISED MAY 14, 1975 **REVISED JAN., 1983**