SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requir	ement of Act /4, Mich. P.	A. 1970 ED 21
KALAMAZOO	Located In:	Corner Code ##	FOR RE FOR RE AM 1
Alamo Township	- 1 C - 12 U		S ZAZE
Public Land Survey	T 1 S R 12 W	K-2	HAZZ ECOI 10 2
	' K		R 7 2 878
	TR		1 .1170
2. Property Controlling	S T R		LIBER I PGIIIV
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		

1. Robert E. Snell, in a field survey on _ _April 28 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned

__ , Recorded Plat _

5. Private Claims ___

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

Description of original monument and accessories and/or subsequent restoration:
1829 - Original Corner set by U. S. Government Land Office Survey-Set & Post.
Beech 12" South 06° West 25 Lks Beech 8" North 88° East 15 8" North 88° East 15 Lks

1876 - Ed Strong County Surveyor-Set Stone. Black Walnut 14" North 14° East 1 Corner Apple 10" North 73°-40' W 79½ Lks 116½ Lks

1893 - Ed Strong County Surveyor-Found Good Black Walnut 12" South 80° West 83 South 80° West 83 Lks Black Walnut 16" North 30° West 87 Lks

1926 - Wilkins and Wheaton Engineering Company-Found Drill Stone
Black Walnut 24" South 80° West 54.7' Black Walnut 30" North 30° West 57.4'
1960 - MSHD-Found Drilled Stone. S 79° W 22.20' 23" Hickory, N 65° E 19.05' 9" Locust,
Description of corner evidence found and/or method applied in restoring or reestablishing corner: S 62° E 26.33' 17

S 62° E 26.33' 17"Hickory

1994 - Wilkins and Wheaton Engineering Company-found drilled stone (6" \times 8" \times 4") with evidence of stake hole below in undisturbed dirt. A 5/8" Rod was found 4.92' South and 3.25' East of drilled stone assumed to be corner set by David Peabody in 1975 (LCRC L.1-P.805). No surface accessories recovered.

> BY KALAMAZOO GOUNT REMONUMENTATION PEER GROUF 7/21/94

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

and faithful perpetuation of the position of the original corner. Placed 16" of 20" Harrison Marker over stone with a Monument Box over.

PK Nail in North Side Power Pole North 52° East 80.96 South 76° West PK Nail in North Side 22.13' (nail/tab 21.84') 34" Walnut 18" Walnut 76.04 North 20° East Nail/Tab PK Nail in South Side Trav. CL of 10th Street 8" Elm South 45° East 38.61' East

FLA id 5 : 10

igned by _

urveyor's Michigan License No. _

Date