

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

J-1 Kalamazoo COUNTY


T 2.S. R 9W

DESCRIPTION OF CORNER North 1/4 Corner Section 2

CORNER MONUMENT Conc. Mon with 1/2" Iron Rod.

DATE MONUMENT PLACED AND WITNESSED 9-18-70

WITNESSES TO CORNER..... S. 26° W. 24.0' 8" TRCC



N. 81° W. 12.0' 3" IRON PIPE

N 40° W 39.8' 6" TRCC

AND

S. 30° E. 26.5' Dead Elm Stub

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

*This corner was recovered using a Dip Needle
AND measuring from Intersection of Eagle Lake Rd.*

SURVEYOR'S SEAL

SIGNED _____

REGISTERED LAND SURVEYOR

DATE _____

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68