

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

M-1

KALAMAZOO COUNTY


T 2.S. R 9.W.

DESCRIPTION OF CORNER N.E. CORNER Section 1

CORNER MONUMENT 1/2" Iron Rod in Conc. Mon.

DATE MONUMENT PLACED AND WITNESSED 9-18-70

WITNESSES TO CORNER..... N 53° W 54.7' Telephone Pole



S. 29° W. 58.4 Power Pole

S. 62° E. 66.7 9" Black Cherry
North one of three

AND
N. 48° E. 27.0 4" x 4" Sign Post

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered

This corner was recovered with a Dip Needle

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68