

## LAND CORNER RECORDATION CERTIFICATE

SURVEY &

For corr	ners in Cha	rleston Twp.	Filing	Requirement of	f Act 74, Mich.	P.A. 1970	0 =	REMO	NUM	ENTA	TION	ř
 _Kalam	aZOO (County)		Located in:	Corner Code	e #		÷	FE	B 08	2000	İ	
1. Publ	ic Land Sur	vey	T <u>2S</u> R9W TR TR TR	B-	05			SE	ECTK	MC		
in Se 3. Misc	erty Contro ection ellaneous erty in Sec.	s s	TR TR TR TR				Regis	ter of De	eds Sta	ımp & F	-ile Num	nber
5. Priva	te Claims  E. Snell  nts of P.A. 74,	, Michigan P.A. (	a field survey on <u>May 20</u> of 1970, the corner poi	ts mentioned in lines 1	and 2 above were in	n	A B	C D E	F G	H I	J K	L 1
United Sta that the co Board of L found as e	tes Departmer orner points me and Surveyors expressed below	nt of the Interior, entioned in lines or by a Decree ov: v:	nerefore as required in t Bureau of Land Manage 3, 4 and 5 above were of a Court of Law; establ	ment or by a decree of in conformance with the ished, re-established, m	a Court of Law and/o e rules of the Michiga onumented, recovered	or n 6	18	20	-16	-15 -22	-14 -23	—13— —24—
NOTE:	Not more the	an 2 corners, a īcale.	ll in the same town ar	d range, may be reco	rded	9 10 11		29	-28	27-	26	
A. Des	cription of	original moπι	ıment and accesso	ries and/or subseq	uent restoration:	12 13	1 1	32	33	_3 <b>4</b>	35	36 
1826:	United Sta	tes Governm /hite Oak 10"	ent Surveyors, J. M N. 53° E.	ullett; set 1/4 Section 32 lks.	on post. White Oak 7"	S. 24° V	<b>V</b> .	38 lks.				
1877:	F. Hodgma	an, County Su	ırveyor; "Found stoı	ne of former survey	. n							
1883:	F. Hodgma Y	an, County Su ellow Oak 12'	irveyor; "Replaced : 'S. 34° W.	stone with 3 ft. of ea 63 1/2 lks.	arthen post with s Yellow Oak 10"	tone arour N. 30° E		100 lks	S.			
B. Des	cription of	corner evide	ence found and/or	method applied i	n restoring or re	establishi	ng cor	ner:				
Circa 19		. Wheaton, C /hile Oak 30"	ounty Surveyor; foւ N. 22°W.	nd tile. 79.50'	Double Locust	N. 25° V	<b>V</b> .	86.57'				
No Date	10	alamazoo Co )" Hickory 4" Elm	unty Witness Book, S. 45° E. N. 40° E.	County Surveyors 52.2' 46.7'	Office; No Desc. 12" Hickory	N. 50° E	<u>:</u>	36.3'				
1999:	Found 1/2" leaning. A	x 18" iron roo t 2.25′ below	d in pavement, a "m surface found 3" ro	ushroom head" fro und tile with "X" on	m tile found 1 ft. t top. Surface iron	pelow surfa was 1.85'	ace 1.9' & 1.62	below su 'East of t	irface f	ound 3' ition of	' round t the tile.	tile,
C. Des	cription of	monument f	or corner and acc	essories establish	ned to perpetuate	e locating	the po	sition of	the co	rner:		
B-05:	as a carefu	ıl and faithfui	7, T. 2 S., R. 9 W., perpetuation of the rveyor in 1883 Ren	position of the origi	inal corner. Foun	d 3" round	tile 2.2	5' below	surface	e, place	d by	
	PK Nail in N PK Nail in S PK Nail in S PK Nail in S	South Side Southwest co		fence post fence post	N. 44° E. N. 84° E. S. 64° E. N. 84° W.	45.41' 29.63' 30.71' 63.74'						
Signed b	y <i>()</i>	ofers	6. Sn	ell	Date	7-	-28	-99	•			
Surveyo	r's Michigan	License No.	9734									<del></del>
		RATI ALAMAZ MONUM PEER ( 7-15-7	OO COUNT ENTATION GROUP	W / /	FORM APPROVED (	BY MICHIGAN	STATE BO	ARD OF PRO	OFESSION	RE	EYORS, JAN EVISED MA REVISED ( REVISED (	Y 14, 19 JAN., 19
			1 1/ /									