SURVEY & REMONUMENTATION

1	1
_	

5. Private Claims

Surveyor's Mionigan License No. ___

APR 2 7 1995


COM	MIS	SIC) N

LAND COOKED DECODDATION CERTIFICATE

	Constitution of the second			rement of Act 74, Mich. P.	
For corners	in		•	•	A. 1970 ERK 30
	(County)		ed In:	Corner Code ##	
Charles 1. Public L	ton Township and Survey	т <u>2</u>	2 S R 9 W	D-9	ARTHGAN OR RECOF
			R R		AN ZOO ORD 18
		τ_	R		_
2. Property	Controlling	S T _	R		LIBER $1_{P0}1242$
in Section	on	s T _	R		上「山上海工行
3. Miscella	neous	S T	R		Register of Deeds Stamp & File Number
Property	in Sec.	s T _	R		
4. Lot No	, Re	corded Plat			., АВС D E F G H I J K L

Robert E. Snell in a field survey on _ May 24 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Set 1/4 Section Post.

9# North East 11 Lks Wh. Oak 70° 10" 43 Lks South West Wh. Oak

S. Hodgman, County Surveyor; Found stake hole, correct by trace of witnesses. Set iron 1872: sleigh shoe and stones. Set side stones North and South (50 Lks).

F. Hodgman, County Surveyor; Found stake, stones and iron for corner and side stones of former survey standing. The road has been filled up over the corner and I left the corner stone in place and put 2' of earthen post over with stones around. 1883:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 6" Piece of tile over stone in monument box and found iron sleigh shoe with stones around 20" below surface. Also, found side stone 50 Lks (33') North.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9734

South 1/4 Post Section 20, T. 2 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 1/2, 1994. Found sleigh shoe as set in 1872 survey by S. Hodgman and mentioned in 1883 remonumentation survey by F. Hodgman and is accepted as a careful and faithful perpetuation of the position of the original corner. Placed 20" Harrison monument with monument box over sleigh shoe.

		5		
Center Line "L" Avenue			4.0'	In Line with fence
PK Nail in East Side	38" Oak		West 31.58	to North
PK Nail in Northeast Side	12" Hickory		East 36.53'	
PK Nail in East Side	15" Red Oak	South 10°		

PK Nail in	12" Q	uad	Cherry	South	52°	West 39.73'	
Signed by John E. In	4/	, 		Date _		12/28/94	