SURVEY &	()					()
REMONUMENTATION						
FEB 2 6 1998	FEB 2 6 1998			LIBER	2PAGE 269	
<i>V</i>	LAND CORNER R	ECORDATION CERT	IFICATE		(9	RE S
SECTION	Filing Requireme	ent of Act 74, Mich. P.	.A. 1970	CLERK	PEC	STATE OF COUNTY OF RECCIVED
For corners in				ER)	1	34. 7.
Kalamazoo	_ Located In:	Corner Code#		1	23	10. 10.
(County) Comstock Township				æ (PA CE	
	2S_R_10W	C-7		EGISTE	<i>N</i> =	A.RE
Τ_ Τ	R			Ħ	1 75	GAI AAZ GCC
<u> </u>				, x	£ 57	DE MICHIGAN DE KALAMAZOO DE FOR RECORD
2. Property Controlling S T_ in Section S T	R					
3. Miscellaneous ST	R					
Property in Sec. S T_	R			Register of De	eds Stamp &	File Number
4. Lot No, Recorded Plat						
5. Private Claims				BCDE	F G H	JKLN
			1 2		43-	_2- -1-
			3			
i, Gary D. Hahn , ir do hereby state that under requirements of	n a field survey on N				910	1112
mentioned in lines 1 and 2 above were in confe	ormance with regulations	and rules therefore as requ	uired 5 🕆		- - - -	
in the current manual of survey instructions of Land Management or by a decree of a Court of	the United States Depar Law and for that the cor	tment of the Interior, Bures mer points mentioned in line	es 3,	-18 17	1615	_1413
4 and 5 above were in conformance with the Decree of a Court of Law; established, re-est	rules of the Michigan Bo	oard of Land Surveyors or	by a 7	*		
below:	.abnsneg, monumented, i	recovered, round as expre	"	19 20	21 22	2324
name of a second section of the state of		b	9 h	_30 _29	28 27	26 - 25
NOTE: Not more than 2 corners, all in the son this certificate.	ame town and range, m	lay be recorded	11			20 25
			12	-3132-	_3334	35-36-
A. Description of original monument and acc	cessories and/or subsequ	uent restoration:	B	ATIFIED		
1827 - Southwest corner established by US (Denuty Surveyor Robert	Clark Ir BY		1AZOO (COUNTY	X
Witness ties: 16" W. Oak S 72 deg	g. E 55 lks.	Clark, or.	REMON	UMENTA	TION	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
18" W. Oak N 63 de 1863 - F. Stimson Vol. 1, Pg. 27 Stone a	g. W 13 lks. and iron stake		PEE	R, GROU	P / W'	
1869 - F. Hodgman Vol. 1, Pg. 60 "This stal		er post No. 18 and is on s	outh side of ro	pad. The distar	ice from H to E	(ESE.) Being
79.65. The true NE corner of section 19 1870 - F. Hodgman Vol. 1, Pg. 136 "Sect			rect Putine	arthen and iror	and marked t	he stane from
which false corner iron bar south 42." S	SE corner freight house N	l 32 deg. W. 87.				
1885 - F. Hodgman Vol. 2, Pg. 243 "Found stone. Nearest corner stone building SW				the iron under	it and put 1 fo	oot post top of
1905 - Ed Strong Vol. 3, Pg. 348 "Tile about			o leed.			
12" Maple S. 20 deg. E. 50½, 13" Pine 1907 - Ed Strong Vol. 3, Pg. 472 "South rail		=	W. 78, Flatiro	on S. 40		
1907 - Ed Strong Vol. 3, Pg. 472 Sodul Tall 1908 - Ed Strong Vol. 4, Pg. 72 "Trolley rail I		elow surface 2 1/3 (eet .				
B. Description of corner evidence found and	d/or method applied in re	estoring or reestablishing c	omer:			
Original monument and accessories no Removed and found clay tile with "X" or						
C. Description of monument for corner and	accessories established	to perpetuate locating the	position of the	e corner:		
C-7, Southwest comer Section 17, Tov 27, 1997. The location of the clay ti						
Harrison Monument in a mon, box over	tile. RR tracks North 26.23 t	foot				.
		теет. n post N 80 deg. W 72.00) feet.	-	WE OF MI	CH, Pe
	crete building S 54 deg. pole South 39.70 feet	E 85.71 feet.		. sri	ZRI.	Call
Set "A nail in power	pole Soudi Sa.70 leet			Addin *	GARY!).
	_			! *		YOR ★
•			.é.		No. 38116	
91 11	r la	. "		T,	NSFD	SURVERBER
Hohn Illa	f/2				38116	111111.
Signed by		·	Date	12/19/97		
Surveyor's Michigan License No. 3811	16					