ST COU REC

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970				19 2	ATE VITY
Kalamazoo (County)	Located In:	Corner Code ##		4 3h	. <u>Cl</u>	0F
Comstock Section 10 1. Public Land Survey	T <u>2 S</u> R <u>10 W</u> T R	<u> </u>		REGISTER	PM 1 37	HICHIGAN KALAMAZOG
	S T R			`		• 0
			Register of	Deeds St	tamp & Fi	le Number
Property in Sec.	S T R					
	orded Plat		A 6	3 C D E	E F G +	H I J K L
			3			
no hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			he 7 15 8 15 fa	3-17-	161	5 14 13
Court of Law; established, re-e expressed below:	established, monumented, re-m	onumented, recovered, found	as 10 3	29	_282	72625
NOTE: Not more than 4 corr on this certificate.	ners, all in the same town and	d range, may be recorded	11 12 3	1 32	33-3	4 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
 - Original corner established by U.S. Government Survey in 1825-Set Post. Wh. Oak 12" North 32°-E 10 Lks (6.6') Wh. Oak 10" South 25°-W 5 Lks (3.3')

1872-F. Hodgeman County Surveyor-found stake from stump of one witness. Plated new stake

Wh. Oak 12" South $11\frac{1}{2}$ °-W 31 Lks (20.46') Wh. Oak 16" North 82°-E $16\frac{1}{2}$ Lks(10.89')

- 1885-F. Hodgeman County Surveyor-found stake corrected by bearing trees of resurvey standing. Set Post.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 3" round tile with "X" on top from 1959 Witness-6" Deep, steel "T" Fence Post on North side of tile. A survey irion is 165'-East of tile.

9" Hickory North 82°-W 2.6'-Gone South 12°-E 61.35'-Gone 20" Oak 13" Oak 27.2' East 18" Oak North 20°-W 32.7'-Gone

Twin 20" Oak South 06°-W 36.9'-Gone

AMAZOO C**OUNTY** REMONUMENTATION PEER GROUP 3-3-94

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - East 1/4 Post of Section 10, T. 2 S., R. 10 W., ratified by Kalamazoo County Remonumentation Program Peer Group on March 3, 1994. Found 3" round tile as called for in 1885 remonumentation survey by F. Hodgeman and is accepted as a careful and faithful perpetuation of the original corners position. Placed remonumentation sleeve over tile.

Date

PK Nail in S side 24" Oak North 60°-W 25.18' South 10°-W South 75°-E 12" Oak 36.15' PK Nail in E side 18" Oak 27.661 PK Nail in N side

15' Oak South 60°-E PK Nail in S side

Signed by Surveyor's Michigan License No. __