STATE - POHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in KALAMA	ZOO T	F WP.	iling Req	uirem	ent of Act 74, Mich.	P.A. 19	7694 MAR 17	PM :	3 3 9)	
KALAMAZOO County)			Located	d In:		Corner Code ##	Jamos	FEG.		,		
1.	Public Land Survey		T T	R R R	- -	D-4		CLERK-R	EGISTE	R		
	Property Controlling in Section Miscellaneous Property in Sec.	· S S	T Т Т	R R R	- -			LIBER			L28 Numbe	r
5. I,do in I cui Ma abo Coi exp	Allen H. McMachereby certify that under reines 1 and 2 above were incent manual of survey instinagement or by a decree of ove were in conformance wurt of Law; established, pressed below: TE: Not more than 4 con this certificate	hema finduirement in conformations of a Court of ith the rule re-establicorners,	eld survey ts of P.A. 74 nance with of the United Law and/o es of the Mi shed, mon	onFe}, Michigan F regulations d States Dep r that the co chigan Boar umented, r	orua P.A. of the and rucerner por rucerner p	ry 7 , 19 94 970, the corner points men ules therefore as required nt of the Interior, Bureau o pints mentioned in lines 3, 4 and Surveyors or by a Decru umented, recovered, fou range, may be recorded	tioned in the f Land I and 5 ee of a nd as	A B C D 2 6 5- 3 4 7 5 6 18 17- 7 8 19 20- 9 10 30 29- 11 12 31 32- 13	E F 9 9 16 16 12 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	G H	2 - 11 14 23 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 26 35 - 26 35 - 26 35 - 26 35 - 26 35 - 26 35 - 26 26 35 - 26 26 26 - 26 - 26 - 26 - 26	12 12 13 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15
Α,		. Hod	geman	C.S. F	21ac	ed Clay Tile ponumentation.		during				,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile 8" below surface

MAZOO COUNTY MONUMENTATION PEER GROUP 3-3-94



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Standard Sleeve over existing Clay Tile, Accessories:

Nail & Tab in West face

Nail & Tab in West face

Nail & Tab in North face

Nail & Tab in East face

8" Maple N. 20 deg. E. 31.19'

12" Apple S. 10 deg. W. 10.26' 7" Maple S. 70 deg. W. 11.97'

12" Double Maple N.10 deg.W. 18.14'

Signed by Surveyor's Michigan License No.

VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983