STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE '94 MAR 3 PM 3 50

For corners in					1							
Kalamazoo (County)	Located In:	Corner Code ##			J.,	-0	92	1.				
Kalamazoo Township				م منه	i en		1	Elecan G		_		
Public Land Survey	T <u>2 S</u> R <u>11 W</u> T R T R	M-12	LIBER	1 P	1	Ô	5 GI:	STER	₹			
2. Property Controlling S												
	T R											
3. Miscellaneous S	T R		Regi	ster o	f Dec	eds :	Stam	p&F	ile f	Num	ber	
Property in Sec. S	T R								<u> </u>			
4. Lot No, Recor	ded Plat				B C	n	E	G	ш	1 1	ĸ	
5. Private Claims				Ê	ΪĬ	Ť	ŤΤ	Ť	ΪĪ	ΪŤ	Ť	Ť
		-		2 ├	┡┼	- 5—	╀╌┋╌	+	3-	— ģ	-	-i
				3	-		++	+	╁╌	┝┵	-	
				4	}	- 8	L.J.		10	_1	_	
I John G. Kester , in	a field survey on Octobe	er 29. 1993		5	LL	Ĭ.	LĬ		Ĭ	1		Ĺ
do hereby certify that under requiren				6 _1				7				
in lines 1 and 2 above were in con-				° 1	*	-17— I	16	1	15	14	-	-13
current manual of survey instruction	ns of the United States Departm	ent of the Interior, Bureau o	of Land	7├—	 		+	\rightarrow	+	\vdash		

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 11

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post established by U.S. Government Deputy Surveyor John Mullett, 1825, set Post, Accessories: Elm 8 N21 W 20; Elm 15 N37W 23. Remonumentation by F. Hodgeman, 1885, Corner lost, bisected line 2-3, set Post (Solid Clay Tile with "X" on top), Accessories: Double Elm 8" N78E 64 Lks. Kalamazoo County Road Commission Found Solid Clay Tile with "X" on top, 1956, Accessories: 28" Elm N80E 43.0'; 14" Maple S50E 45.60', Set construction witnesses, removed Tile during construction (cut 6'). W.D. Ingersoll set ½" Iron in 1957 from Road Commission construction witnesses. Kalamazoo County Road Commission found Ingersoll Iron in 1993, replaced with 30" Harrison Monument in Monument Box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner Post and Accessories not found. Found 1/2" Iron in Monument Box established by Ingersoll from Road Commission construction witnesses of Tile set by F. Hodgeman during Remonumentation in 1885.

> LAMAZOO COUNTY REMONUMENTATION PEER GROUP 1-20-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-12, E1 Corner Section 36, T2S-R11W, Ratified by Kalamazoo County Remonumentation Program Peer Group on January 20, 1994. Found 12" Iron in Monument Box set by Ingersoll in 1957 from Kalamazoo County Road Commission construction witnesses of Solid Clay Tile with "X" on top called for in 1885 Remonumentation and is accepted as a careful and faithful perpetuation of the Original Corner position. Removed Monument Box, replaced 17" Iron with 30" Harrison Monument, placed Monument Box over Corner.

31.95 Set 3" Rebar at Back of Curb West Set 2" Rebar at Back of Curb 32.10' East S 50° E 40.56' S.W. Corner Inlet Casting s 10° W 27.61 Center of Storm Manhole

Signed by	John St. Blance
-----------	-----------------

2-28-94

Date