## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

Located In:

For corners in KALAMAZOO COUNTY

1. Public Land Survey  T 2S R 12W K-1 T 2S R 12W K-2	
T R	
T R	
2. Property Controlling S T R	
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Property in Sec. S T R	
4. Lot No, Recorded Plat A B C D E F G H I J K L M	
5. Private Claims	2 6 5 4 3 2 1
	3
I, SARY C. BILOW , in a field survey on JULY 2 , 19 90	4 - 7 - 4 - 9 - 10 - 11 - 12 - 12 - 15 - 12 - 13 - 12 - 13 - 12 - 13 - 13 - 13
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	
Court of Law; established, re-established, monumented, re-monumented, recovered, fou expressed below:	nd as
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	· <sup>¹¹</sup> ┡ <del>╅┥┩</del> ╏┼┼┼┼┼
on this certificate.	12 -31 -32 -33 -34 -35 -36 -1 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original monument and accessories and/or subsequent restoration:	
K-1: CORMER ESTABLISHED BY U.S. GOV'T DEPUTY SURVEYOR 6. HARRISON IN 1830:ACCESSORIES - BEECH 6,559E,53 & BEECH 6,525W,27.  COUNTY SURVEYOR HODGEMAN RECORDED THREE WITNESSES (SUBAR 30,550W,14 - ASH 8,521E,30 - WALNUT 6,535E,37) BUT NO MENTIGN	
OF WHAT FOUND OR SET IN COUNTY SURVEYOR RECORDS (FIRM OF WILKENS & WHEATON HAVE COUNTY SURVEYOR RECORDS) IN LATE	
1800'S. WILKINS & WHEATON RECORDED IN SAME RECORDS "PLACED 1/2" IRON FROM WITNESS TREE - NEW ACCESSORY: EAST 232' A	
FENCE GOING NORTH. FROM RECORDS OF GOVE & ASSOCIATES DATED 1962 - 1/2" IRON ROD IN MONUMENT BOX - ACCESSORIES: FENCE POST, N65N, 52.91'-FENCE POST, S7N, 32.80'-FENCE POST, S45E, 45.46'-48" ELM, S65E, 65.25'.	
K-2: CORNER ESTABLISHED BY U.S. GOV'T DEPUTY SURVEYOR 6. HARRISON IN 1830: ACCESSORIES - BEECH 12, N24W, 10 & BEECH 15, 587E, 39.	
COUNTY SURVEYOR HODGEMAN RECORDED IN LATE 1800'S "STONE IN CENTER OF RAILROAD-ACCESSORIES: RED DAK 18,N7W,56-WHITE DAK 9,871E,77-STONE,NORTH,85." FROM GOVE ASSOCIATES RECORDS DATED 1957 "SET T-IRON FROM 2 WITNESS POINTS FROM WILKINS."	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
K-1: FOUND 5/8" IRON BAR IN MONUMENT BOX AND ACCEPTED THIS CORNER AS THE BEST EVIDENCE OF THE ORIGINAL GLO CORNER.	
K-2: FOUND 1/2" IRON BAR IN MONUMENT BOX AND ACCEPTED THIS CORNER AS THE BEST EVIDENCE OF THE ORIGINAL GLO CORNER.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
	ON BAR IN MONUMENT BOX
	NAIL & MONR TAG IN GUARD RAIL POST NAIL & MONR TAG IN UTILITY POLE
	MAIL & MONR TAG IN 5" POPLAR
	NAIL & MONR TAG IN GUARD RAIL POST
SSOE 52.50', NAIL & MONR TAG IN NORTH SIDE GUARD RAIL POST	Server OF Models
S45M 61.21', NAIL & MONR TAG IN 12" ELM	
	GARY C. BILOW
	A LAND
Signed by Date	5/22/91 SURVEYOR
Surveyor's Michigan License No. 26453	26453
LAND at vinetillar 1863	
PAGE 22	