SURVEY & REMONUMENTATION

Surveyor's Michigan License No.

7 SEP 1 4 1998 -	 ! (0.00				
V	LIBER	ZΡ	AGE 2	294	
SECTION LAND CORNER RECORDATION CERTIFICATE	_		ശ്	Z C	
Oshtemo Twp. Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Kalamazoo	2	1.1		으 두 뭐	
Located In: Corner Code #	CLERK	J	======================================	NTY EIVE	
	1	N.		무수학	
1. Public Land Survey T2S _R 12WF-5	<u> </u>	¥.>	(
T R	ć (7)	V.			
T R	-i		ယ	0150 434 1 4374 Z Z Z D D	
T R	ä	£.	- · ·	3 3 5	
2. Property Controlling S T R		Ġ. ;	ເວ : ~1 :		
in Section S T R				0	
3. Miscellaneous S T R	ster of D	eeds Sta	ımn & I	File Numb	ar.
Property in Section 3 i i i				- IIC HOILE	
4. Lot No, Recorded Plat					
5. Private Claims	Î	CPE	- F G	<u>H J</u>	K L
	2 6				+-1
	3	+++		1	+-+
Allen H. McMachen	4 }-		-ģ-+	-1011-	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	5	 - - 	+ +	+ + +	+
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current	6 18	 - 7- -	-16	-1514-	13
manual of survey instructions of the United States Department of the Interior, Bureau of Land	7	+++		+++	+
Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a	8 - 19-	20-	21-	22 23	24
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found	9	 - - 	++		+
as expressed below:	10 30-	29	-28	27-26-	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	11	 	++	+++	++
on this certificate.	12 31	32	-33- -	-3435- 	36
A. Description of original monument and accessories and/or subsequent restoration:	101	-`\			
1830 - George W. Harrison, D.S., Set ¼ Section post, Bl. Oak 3" N. 80½° E. 149 lks., Wh.	O I 4" >	T 41 40			
1873 - Ed Strong, C.S., Y. Oak 5" S. 50° E. 2 lks Found U.S	Oak 4 N	iorth 194	4 IKS		
1908 - Ed Strong, C.S., "Found marked stone at bearing tree."					
B. Description of corner evidence found and/or method applied in restoring or reestablishing	corner:				
Found pointed stone at intersection of tree rows North, South, East & West. Stone meas.	1′ X 1′ X	15'			
	R	ATIF	ΕD		
BY				OUNT	V
F	EMON	MME	NTAT	TION	•
·		R G			
	2	-19-190	18 /	298	
			' l	<i>r</i> .	
'					
C. Description of monument for corner and accessories established to perpetuate locating the	position	of the c	orner:		
					
Found Pointed Stone is accepted as a careful and faithful perpetuation of the position of		WHITHIN S. C.	Manager	iggie.	
the original corner, kelmoved stone and replaced with 30" Harrison Monument at	فيجيد	1 E	M / C	4	
location of point of stone, Accessories:	JANA V	Al i	LEN H.	\ C, \ \	
Nail in West side 5" Hickory N. 10° E. 5.90'	# "	•	IACHEN	*\ <u>\</u>	
Nail in North side 12" Hickory S. 60° E. 4.85'	7	i	ESSIONAL	1 1	
Nail in Northwesterly side 10" Hickory S. 60° W. 11.68'	10		RVEYOR No] }	
Nail in North side 10" Hickory West 16.30'	T CE	•	No. 8935	151	
		*		SURPLANT OF SURPLA	
$\bigcap_{i \in \mathcal{I}} \mathcal{I}_{i} = \mathcal{I}_{i$	/3	************	SSIONAL	Market Mark	
Signed by Date 2/2	4/98	Market C. E.	****	••	
10.02	-,				

BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983