FEB 1 8 1994

				တို့ အဝ
1 - COMMISSION 2 - For gorners in		R RECORDATION CERTIFICATE ment of Act 74, Mich. P.A. 1970	L 2 1	STATE OUNTY O RECEIVE
* Kalamazoo	Located In:	Corner Code ##	- RECIST	OF MIC OF KAL D FOR I
1. Public Land Survey 1/4 Sec. Cor. 14, 23	T 2 S R 12 W T 2 S R 12 W T R T R	J-7 J-7	TER	HIGAN AMAZOC RECORD
in Section S	_ T R _ T R		LIBER	PC 997
	_ T R _ T R	Re	gister of Deeds S	Stamp & File Number
4. Lot No, Recorded 5. Private Claims	Plat		A B C D	E F G H J K L M
t, Robert E. Snell in a field do hereby certify that under requirements in lines 1 and 2 above were in conforma current manual of survey instructions of the Management or by a decree of a Court of Labove were in conformance with the rules Court of Law; established, re-establish expressed below:	of P.A. 74, Michigan P.A. of nce with regulations and he United States Departm awand/or that the corner of the Michigan Board of	f 1970, the corner points mentioned rules therefore as required in the nent of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a	4 - 7 - 8 - 5 6 - 18 - 17 - 7 8 - 19 - 20 9 10 - 30 - 29	9 - 10 - 11 - 12 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 15 - 14 - 15 - 14 - 15 - 14 - 15 - 14 - 15 - 14 - 15 - 15
NOTE: Not more than 4 corners, all on this certificate.	I in the same town and	I range, may be recorded	11 12 31 32	33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
 - Government post set December 1829. Ed Strong 1883: S. ¼ on corner fence post, stump good. 1961 Ingersoll set iron rod for S. ¼ post at bisection of S. line of Section 14.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found iron rod set by Ingersoll in 1961 from Ingersoll witness. Witness: RR tie fence post N. 85° E. 2.1 feet.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

\$5-20-93

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The iron placed by Ingersoll is accepted as the best available evidence of the original corner position and the iron was replaced with a 30" Harrison Monument. Witness 1. Tab/PK nail in 8" multiple (6) Wild Cherry - W. 19.12 ft.

2. Tab/PK nail in RR tie fence corner - N. 70° E. 2.18 ft.

3. Tab/PK nail in 12" Oak - N. 75° E. 10.74 ft.

4. 24" Wild Cherry - N. 10° E. 64.24 ft.

and the	3L 1
Signed by	(prol)
Surveyor's Michigan License No.	9734
<i>(</i>	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971

REVISED MAY 14, 1975