STEAL BENOMINE.

expressed below:

on this certificate.

AUG 2 2 1995

## LAND CORNER REGORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

'95 APR 26 AM 11 09

For corners in COMMIS	SECTION Filing Require	ement of Act 74, Mich. P.A	1970 '95 APR 26	AM 11 09
Kalamazoo	Located In:	Corner Code ##	0	
Oshtemo Township		1 11		Just
Public Land Survey	T <u>2 S R 12 W</u> T R	<u>J-11</u>	CLERK - F	REGISTER
	T R		LIBER	1 11292
Property Controlling     in Section	S T R S T R			
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds St	amp & File Number
4. Lot No, R	Recorded Plat		A B C D E	E F G H I J K L M
5. Private Claims			2 6 5	3
•			3 4 7 8	9 10 11 12
Robert E. Snell	in a field survey onJune quirements of P.A. 74, Michigan P.A. 0	e 10 19 94 of 1970, the corner points mentio	oned 6 18 17	
in lines 1 and 2 above were in current manual of survey instru	n conformance with regulations and uctions of the United States Depart	d rules therefore as required in tment of the Interior, Bureau of L	the and 7	16 15 14 13
management or by a decree of a	a Court of Law and/or that the corner	i points membored mines s, 4 ai	11U 5 8 19 19 20 1	<u>21+-22+-23+-24</u>

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

U.S. Government Survey; Set 1/4 Section Post.

05° Bl. Oak 9" North **Fast** 

5" 61 1/2° W. Oak South East 24 Lks

1874: Ed Strong, County Surveyor; Iron and stone of former survey

> 5" Sugar South 58° East 47 Lks 64° 5 <sup>II</sup> Sugar North 48 Lks East

1928: Kalamazoo County Road Commission; South 1/4 Post Section 26, iron stake (field notes)
Maple 18" S 30° E 52.9' Maple 6" S 30° W 56.3' Walnut 14" S 80° E 80.8'
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/8" x 18" iron in monument box. Below this iron was found an older 1/2" x 12" iron. Dug a 4' x 4' hole to a depth of 4' and found nothing futher. Dug to about 7' with post hole digger and found no other evidence.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 4-20-95

10

12

C.	Description of monument for corner and	accessories established to perpetua	te locating the position of the comer.
----	--	-------------------------------------	--

J-11 South 1/4 Post Section 25, T. 2 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on April 20, 1995. Found 1/2" x 12" iron  $2\frac{1}{2}$ ' below surface and is accepted as a careful and faithful reestablishment of the position of the original corner. Placed a 20" Harrison monument and monument box in place of iron.

Date \_

North 64° West South 58° West South 32° West Exist. PK Nail in North Side 14" Maple 49.321 50.35 Exist. Nail/Tab in Telephone Pole 93.131 PK Nail in Southeast Side of Power Pole Concrete Light Pole Base South 80° East Nail in Southwest corner of

0.113		11
Signed by // FAM C.	The	U/_
Surveyor's Mighigan License No.	9734	

4-26-95

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983