## SURVEY & REVORMENTATION

FEB 1 8 1994

## LAND CORNER RECORDATION CERTIFICATE

STATE CE MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

COMMISSION For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

'93 NOV 29 PM 2 21

(County)	L	Located II	ก:		Corner	Code =	#			(	1								
Climax Township	•		_			_				_>	Sir		وكمص	2	وسدي	مسلت	/		
1. Public Land Survey			R 9 W	_	G	<del>-</del> 9								v	0				
	-	Τ	R	_							CL	ERK	- RE	GIS	TER	į.			
	-	Τ	. R	_	· ·								•	-					
-		T	R											_		_			
2. Property Controlling	S	. T	. R	_							LIBI	TD.		1	pr1		38	! !	
in Section	. s	. T	. R	_							LIDI	-11	•		1 U_E	_ •	•	,	
3. Miscellaneous	. S	.T	R	_				· 1	Registe	er of	Dee	ds :	Stan	<b>2</b> 0	File	Nun	nbei	r	
Property in Sec.	S	T	R	_	·				<b>J</b>										
4. Lot No, 1	Recorded Pl	lat								A E	C	D	E	: G	н	ı	ĸ	L	ı
5. Private Claims										ГТ	Т	Ī	Ī	丁	Т	П	T	Ť	_
·.									2		+	-`5	+-4	+	- 3	— <u>?</u>	!	<u></u> 1 -	-
									. 3	$\vdash$	+	+	+	+	┿	╂╌┤	-		-
									4	┝┆	-	- 8—	<b>-</b> ↓- å	+	-10	<del> </del> 1	1—	-12	<u>.</u>
I John G. Kester	, in a field	survey on	<u>Au</u>	.gust	<u>10</u>	· ,	. 19 <u>93</u>		5		4	4	$\sqcup$	$\dashv$	$\bot$	┷		_	
do hereby certify that under re									-6		$\perp$	 -17—	$\perp$	<u>.</u>	 -15	ĻĮ	4	_  13-	<u>.                                    </u>
in lines 1 and 2 above were i	n conforman	ce with re-	guiations a	and rule	as theref	rore as r	required	in the		Ιï		ï	1 ï		ĩ	1 1	ıl	ï	

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

10

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post established by U S Government Deputy Surveyor Robert Clark, 1826,

Accessories: Elm 18 S53E 22, B Ash 13 N34W  $22\frac{1}{2}$ .

Survey by Ed Strong, 1872, Found Stake, set square Stone with Drill Hole, Accessories: Side Stone North 50 Lks, B Ash 20 N71 Lks, Maple 12 S40 3/4E 93 Lks. Remonumentation by F. Hodgeman, 1883, Found Stone of resurvey and remains of old Stake under it. Stumps of U S witness trees and of resurvey are standing, also side Stone 50 Lks South. Bored 3', filled 2' with broken Brick and Stones, I Earthen Post over and Stone around it. Accessories: W Ash 8 N43 $\frac{1}{2}$ W 90 $\frac{1}{2}$  Lks, Elm 6 N2 E 78 2/3 Lks. LCRC by M. E. DeKeyser, 1973, Found existing Iron, Accessories: R.R. Rail Fen Cor S 31.0', U Pole N45W 66.92', 12" Maple Clump N15E 72.40'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner and Accessories not recovered.

Found 1/2" Iron in Monument Box believed to be same as recorded in 1973 LCRC by M. E. DeKeyser.

Found 19" Pipe 3.75' South and 0.67' East of 19" Iron in Monument Box. Found Solid Clay Tile with X on top, 3.62' South & 1.13' East of  $\frac{1}{2}$ " Iron in Monument Box and 36" below road surface, with large Stone on West side and small Stones & Brick under Tile as called for by 1883 Remonumentation by F. Hodgeman.

## RATIFIED BY KALAMAZOO COUNTY **REMONUMENTATION** PEER GROUP

9-16-93

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-9, Corner of Sections 21, 22, 27 & 28, T3S-R9W, Ratified by Kalamazoo County Remonumentation Program Peer Group on September 16, 1993. Found 2" Iron in Monument Box and 2" Pipe are incorrect. Found Solid Clay Tile with X on top over Brick & Stones by 1883 Remonumentation and is accepted as a careful and faithful perpetuation of the Original Corners position. Removed 2" Iron, Monument Box and Pipe. Placed 20" Harrison Monument above Solid Clay Tile with X on top and placed Monument Box over Corner.

Set P.K. Nail in 9" Cottonwood S45E 30.17 Center/Top R.R. Rail Fence Post South 27.25' Set P.K. Nail in P.P. N45W 47.40' Set P.K. Nail in 11" Ash North 47.16'

Signed by	But -	Date <u>11-26-93</u>	 
Surveyor's Michigan License No.	16046		