OCT 0 6 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Climax Twp.

r -	
Located In:	Corner Code #
T 35 F	<u> 9W H-11</u>
TF	
T	
T F	<u> </u>
s <u>_</u> !	<u></u>
	<u> </u>
S T!	<u> </u>
s T	R

2PAGE 157 LIBER


OF KALAMAZOO

Register of Deeds Stamp & File Number

4. Lot No	Recorded Plat
5. Private Claims _	

, in a field survey on $\frac{1}{2}$ une $\frac{30}{2}$, 19 $\frac{97}{2}$ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the conformance with regulations and rules trerefore as required in the current mention of survey management of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Law and Jones States Department of the Interior of Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
 - 1825: United States Government Surveyors; set 1/4 Section post.

Sugar 11"

N. 32° W.

10½ lks.

21 1ks.

s. 14° E. F. Hodgman, County Surveyor; "Found large boulder with hole drilled in it for corner, 1883: by R. Nutting.

Hickory 5"

s. 39° W.

53 1ks.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Found large boulder with hole drilled in it $(1/2" \times 1/2")~0.65'$ below surface of bituminous road. Found Hickory tree (40") S. 39° W. 53 lks. (34.98') from 1883 (5").

RATIFIED AMAZOO COUNTY EMONUMENTATION PEER GROUP 7-16-1997

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
 - South 1/4 post, Section 27, T. 3 S., R. 9 W.; ratified by the Kalamazoo County Remonumentation Program Peer Group on July 16, 1997 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found large boulder set by R. Nutting, Surveyor and found and accepted in 1883 Remonumentation Survey by F. Hodgman, County Surveyor. Placed 5" of 10" Harrison Monument in concrete over drill hole in stone and placed 1 1/2" Paving Riser with cap over monument.

PK Nail in West Side

18" Maple

40" Hickory

S. 39° W.

35.40'

PK Nail in West Side PK Nail in East Side

6" Hickory

S. 06° E.

18" Hickory

N. 62° E.

32.441

PK Nail in Southeast Sjde Dofers

Signed by_ Surveyor's Mighigan License No.

9734