## REMONUMENTATION

## FEB 1 8 1994

For corners in COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

			HIGAN
COUNTY	J =	KA	AMAZ00
RECEIVE	D. F	OR	RECORD

'93 NOU 29 PM 2 22

James Cham
Daniel June
CLERK-REGISTER

Katania200	Located in:	Corner Code =##		$\mathcal{C}$					
Climax Township		-		$\rightarrow$	Lann.	ce g	Free	مسيي	,
Public Land Survey	T3 S R 9 W	<u> </u>					-		
·	T R				CLERE	-REG	ISTE	R	
	T R								
	T R				4	4.04	lo"		
2. Property Controlling	S T R		LIBER	! .	I Pi	104	ŁU		
in Section	S T R								
3. Miscellaneous	S T R	***************************************	Registe	r of D	eeds S	amp &	File (	Numb	er <sup>'</sup>
Property in Sec.	S T R				··· ·		<del></del>		
		•							
	ecorded Plat			А В	C D I	FG	н 1		K L M
5. Private Claims	<u> </u>	<u> </u>		Ţ				Ι.	
			-	— 6 	1-1-1	-1-1	-3	— 2 — 	<b>†</b>
								- <del></del>	1-1-1
			. 4	Ż	┝╌┆╾╅	<del> </del>	-1'0	—11— 	12
	in a field survey onAug uirements of P.A. 74, Michigan P.A. o						+	$\vdash$	+
	conformance with regulations and	- · · · · · · · · · · · · · · · · · · ·		-18-	17	16	-15-	<u>1</u> 4	<del>   </del>  3-
	ctions of the United States Departr		_	+		-	$\dashv$		+
	Court of Law and/or that the corner	· ·	~ ;	19	_20	21	_22	23	24
	the rules of the Michigan Board of								
expressed below:	-established, monumented, re-m	bridillerited, recovered, Todrid	as 10	30		_28	_  ] _27		25_
•	rners, all in the same town and	d range may be recorded	11	Ĭ	ĬĨ	Ĩ l	Ĩ	LÏ	
on this certificate.	iners, an in the same town and	u lange, may be recorded	12						
On this Continuate.	•		10	—31— 	32   	-33-1	<b></b>	35	1
A Description of outside to	anument and accompanies and	/or outpossuppt rootoration:	141						

Corner Post established by U S Government Deputy Surveyor Robert Clark, 1826, Accessories: Elm 8 N66W 64, Maple 9 N68E 73.

Remonumentation by F. Hodgeman, 1883, Found Stake standing and witness trees of resurvey alive and good. Put down 3' Earthen Post and remeasured witness trees. Accessories: Elm 8 N57W 23 Lks, Elm 6" N312E 59 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner and Accessories not recovered. Found 12" Iron - Found Solid Clay Tile with X on top, 0.37' South and 1.28' West of ½" Iron and 50" below road surface, as called for in 1883 Remonumentation by F. Hodgeman.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

9-16-93

C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:
	I-9, Corner of Sections 22, 23, 26 & 27, T3S-R9W, Ratified by Kalamazoo County
	Remonumentation Program Peer Group on September 16, 1993. Found Solid Clay Tile
	with Y on top and is accepted as a careful and faithful perpetuation of the
	Original Corners position. Removed 2" Iron. Placed 30" Harrison Monument above
	Solid Clay Tile with X on top and placed Monument Box over Corner.

Set P.K. Nail in 6" Fence Post N9W 32.73' Set P.K. Nail in 6" Fence Post N55W 54.22' Set P.K. Nail in 35" Poplar S20E 47.25' Set 16 Penny Spike in 8" Fence Post S60E 60.96'

^		•	
Signed by	2 2 2 2 2 m	Date11-29-93	 _
signed by			