For corners in Climay Two

2PAGE 371 LIBER

LAND CORNER	RECORDA	TION CE	ERTIFICATI
Filina Requiren	nent of Act 7	74. Mich.	P.A. 1970

TO COMMON OF THE A	ν.	
Kalamazoo (County)	Located In:	Corner Code#
1. Public Land Survey	T <u>3S_R</u> TR_ TR_ TR	9W J-11
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR	

FOR RECOR MICHICAN

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat_		
5. Private Claims			

, in a field survey on <u>Feb. 4</u>, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RATIFIED BY KALAMAZOO COUN REMONUMENTATION

A. Description of original monument and accessories and/or subsequent restoration: United States Government Surveyors; set 1/4 Section post.

> N. 31⁰ W. S. 56⁰ E. Sugar 18"

Beech 6"

31 1ks.

F. Hodgman, County Surveyor; found large granite boulder with drill hole for corner, 1883: set by R. Nutting and side stones 50 1ks. each North & South.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1972: Wilkins & Wheaton Engr. Co.; found drilled stone, SE corner of house Northwest 135.22', "T" iron street post Northeast 47.35'

Wilkins & Wheaton Engr. Co.; found drilled stone, 42" Maple Southwest 21.0', 10" Poplar N. 25^{0} E. 62.0', 20" Maple N. 80^{0} W. 120.0'1977:

Found large granite boulder with 5/8" drill hole about 4" below surface 1998:

Noted 1972 witnesses good 1976 Maple N. 80° W. 120.0' good

1983 Side stone South 33'+

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 post, Section 26, T. 3 S., R. 9 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on February 19, 1998 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found large granite boulder with drill hole and a side stone 33' South as verified by F. Hodgman, County Surveyor in 1883 Remonumentation survey. Placed 3" of 6" Harrison monument in concrete over drill hole.

10" W. Cherry PK Nail in East Side 14" Maple PK Nail in East Side 12" Maple PK Nail in North Side Power Pole PK Nail in East Side

S. 20° W. S. 58° W. 33,621 55.49 s. 70° Ε., 95.19^t 26⁰ 96.99 N. Ε,

Signed by Surveyor's Michigan License No

Date