SURVEY & REMONUMENTATION

SEP 1 4 1998 2PAGE 286 LIBER SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Pavilion Twp. For corners in Kalamazoo , Located in: Corner Code # 3S. _R 10W. 1. Public Land Survey Т 2. Property Controlling _ T __T in Section 3. Miscellaneous T Register of Deeds Stamp & File Number Property in Section , Recorded Plat Private Claims I, Allen H. McMachen , in a field survey on November 10 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: 1827 - Robert Clark, D.S., Set 1870 - F. Hodgman, C.S., "Quarter 1888 - F. Hodgman, C.S., "Found quarter Section post, W. Oak 13" N. post said by Smith to have been stone which Elijah Smith says he 36° E. 36 lks. W. Oak 24" S. 17° W. kept in place of original set by put in place of the original stake Watson, County Surveyor. Stakes which he has kept up for 53 years. 1865 - F. Stimson, C.S., "Found planted when witnesses were He says the stone is 3' long & 2' good." stake said by A.H. Smith & E.S. square at the base. Sycamore 18" N. Smith to have been kept in place of 1872 - S. Hodgman, D.C.S., "Found 74° E. 117 lks., Maple 12" S. 21° E. original stake. Trees & stumps stake" 119 lks.. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

Found drilled stone per (2) 1888 witnesses. Drill hole had large iron bolt in it.

RATIFIED BY KALAMAZOO COUNT REMONUMENTATION
PEER GROUP

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Found stone is accepted a careful and faithful perpetuation of the position of the original corner. Broke off top 2" and placed 6" of Harrison Monument over drill hole (in concrete), placed monument box over., Accessories:

Nail (existing) in U. Pole N. 50° W. 67.3' Nail (existing) in 24" Maple S. 40° W. 61.30' "PK" Nail (existing) in 42" Sycamore (1888 Hodgman) N. 75° E. 77.3' Nail (existing) in 32" Maple (1888 Hodgman) S. 20° E. 79.40"

Signed by Surveyor's Michigan License No.

MICH ALLEN H. McMACHEN PROFESSIONAL SURVEYOR No. 16935 PROFESSIONAL

WI STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REPRESED MAY 14 107