## FEB 1 8 1994

7-	

COMMISSION

1 pt 1678 LIVER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in PAVILION TWP.

KALAMAZOO (County)			Locate	d In:	Corner Code ##		
1.	Public Land Survey	•		S R 10W	C-13		
			Τ	R			
			T	R			
2.	Property Controlling	S	T	R	·		
	in Section	S	T	R			
3.	Miscellaneous	· S	T	R			
	Property in Sec.	S	Ť	B	· · · · · · · · · · · · · · · · · · ·		

Register of Deeds Stamp & File Number

5	D-1 1 -	Claims
	PINAIP	Caramis

I, Allen H. McMachema field survey on December 4 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1888 - F. Hodgeman C.S. placed Clay Tile post during official Township Remonumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile 0.5' deep.

## RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

12-16-93



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Standard Sleeve over existing Tile, accessories:

Nail	in	West	face	12"	Cherry	N.	28	deg.	Ε.	29.57
Nai1	in	South	face	Util	. Pole	S.	82	đeg.	E.	29.03'
		South		12"	Hick.	N.	78	deg.	W.	12.23'
Nail	in	South	west face	Uti1	. Pole	N.	18	deg.	W.	52.64

Date

Surveyor's Michigan License No.

BY MICHIGAN STATE BOARD OF LAND SURVEYDRS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983