SURVEY & REMONUMENTATION

APR 27 1995

STATE OF MICHIGAN · COUNTY OF KALAMAZOO RECEIVED FOR RECORD

COMMISSION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'94 DEC 6 PM 3 56

	alamazoo			1		ال رو موسود	م م محمد مسال د س	/
	(County)	Located In:	Corner Code =	#		l	James .	
	avilion Township Public Land Survey	T 3 S R 10 W T R T R T R	D-13		•	CLERK - RE	EGISTER	
2.		T R			LIBER	1 PG11	88	
2		T R T R						
J.		† P T R		Re	gister of D	eeds Stamp	& File Nun	nber
	Froperty III Sec. S	/ P				·		
	Lot No, Recorde			•	A B	CDEF	G H I J	KLM
ψ.					2 6	 54	32	
					3		\downarrow	
		_	_		4 - 7-	8		1212
1,	Robert E. Snell , in a fi				5		\longrightarrow	_
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned							13-	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land								
	nagement or by a decree of a Court o		•		819	_2021	22 2:	3
	ove were in conformance with the ruur rt of Law; established, re-establ				9			
	ressed below:				10 30	2928	27-26	25
NO	TE: Not more than 4 corners,	all in the same town ar	nd range, may be re	corded	11		+	- -
	on this certificate.				12 -31-	3233	34-35	36
Α	Description of original manuscript	ant and pagesagring an	d/a= =h=a==+		13	O		
Α.	Description of original monume					•		
	1827 - U.S. Governmen	t Survey-Set Pos	t, Corner to 1	./4 Section				
	Wh. Oak Wh. Oak	18" East 10" North	71½° West	303 Lks 33 Lks				
	1874 - F. Hodgeman, C Set stone and		ound stake fro	om hole wher	e one wi	tness had	l been r	emoved
	Wh. Oak Pine 1888 - F. Hodgeman, C	10" South	15½° East				in place	. Set
В.	Description of corner evidence	found and/or method a	applied in restoring	or reestablishing	corner:		•	post
	1994 - Found two (2)	irons $(\frac{1}{2}$ " x 18")	in monument b					
				BY KA	HATIF LAMAZI MONUM PEER 7/2	JED COU DO COU JENTATIO GROUP	WYN N. Carlon	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: South 1/4 Post Section 32, T. 3 S., R. 10 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 21, 1994. Found 3" round tile as called for in remonumentation survey by F. Hodgeman in 1888 and is accepted as a careful and faithful perpetuation of the original corner's position. Removed irons and placed 12" of 20" Harrison monument over tile with monument box over.

Notch in Top of RR Rail Fence Corner North 32° East 51.19' PK Nail in Northeast Side 14" Cedar South 52° East 64.84' PK Nail in Northeast Side 14" Cedar South 52° East 64.84' Northeast Corner of House Foundation South 08° West 59.13' Northwest Corner of House Foundation South 29° West 65.40'

CL "T" Avenue North 0.5' CL 27th Street East 0.55'

North 1/4 Post Sec. 5, Brady East 26.55'

Signed by What E.	Froll
Surveyor's Michigan License No	9734