

FEB 1 8 1994

1 PG 1086 LICER

7	ノ
1	
ð	

4. Lot No. _

COMBECON

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in PAVILIO	N TWP.		<u> </u>
K	ALAMAZOO (County)	Located In:	Corner Code ≠≠	CLE CLIN
1.	Public Land Survey	T <u>3S</u> R <u>10W</u> T R T R	₩-3	Y OF KALI VED FOR R VED FOR R ERK-RECIS
2.	Property Controlling in Section	S T R S T R		HIGAI AMAZ RECO 3 C
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & Fife Number

5. Private Claims

____ , Recorded Plat

I, Allen H. McMachen a field survey on December 4 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1888 - F. Hodgeman C.S. placed Clay Tile post during official Township Remonumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Clay Tile 1' deep.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

12-16-93



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful and faithful perpetuation of the original corner. Placed Standard Sleeve over existing Tile; accessories:

Nail in East 8" Quad Cherry face N. 23 deg. W. 28.19' Nail in Southeast face 5" Oak S. 23 deg. W. 55.35 30" Oak Nail in South face 77 S. deg. E. 33.891 12" Triple Cherry SOUTH Nail in South 37.40'

Signed by Surveyor's Michigan License No.

PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 REVISED JAN., 1983