AUG 2 2 1095

COMMISSION

STATE OF HOMESAN COUNTY OF TALAMAZOO RECEIVED FOR RECORD

## LAND CORNER RECORDATION CERTIFICATE

For corners in PAVILION	Filing Requ	irement of Act 74, Mich. P.A. 1	1 <b>970</b> 195 Filli 2	3 PH 4 09
KALAMAZOO (County)	Located In:	Corner Code #	Jan	es freeze
Public Land Survey	T <u>3 S R 10</u> T R T R T R		OLER	K-REGISTER
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Section</li> </ol>	S T R S T R S T R S T R			PC1283
I, Allen H. McMachi do hereby certify that under require in lines 1 and 2 above were in commanual of survey instructions of Management or by a decree of a 5 above were in conformance with the survey instructions of the survey in th	eanfield survey on <u>Janua</u> rements of P.A. 74, Michigan I formance with regulations and of the United States Depar Court of Law and/or that the the rules of the Michigan shed, re-established, monuments	ry 12 19 95  P.A. of 1970, the corner points mentioned rules therefore as required in the curre trnent of the interior, Bureau of Lar corner points mentioned in lines 3, 4 ar Board of Professional Surveyors or by ented, re-monumented, recovered, four	2 — 6 — 3 3 4 — 7 — 7 — 7 — 7 — 7 — 7 — 7 — 7 — 7 —	D E F G H J K L N 5
A. Description of original me	onument and accessories	and/or subsequent restoration:		

- - 1827 R. Clark, D.S., Set Quarter Section Post W. Oak 13" N. 62° W. 39 1ks. W. Oak 16" N. 75° E. 14½ 1ks.
  - 1888 F. Hodgeman, C.S., Found Stake S. 75° W. 14½ 1ks. from stump of bearing tree, Set Post. W. Oak 16" S. 47½° E. 23 lks. V. Oak 3" N. 3° W. 34½ lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Clay Tile 0.4' below surface, 1.2' South of fence corner.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Clay Tile is accepted as a careful and faithful perpetuation of the position of the original corner. Placed Standard sleeve over existing Clay Tile. Accessories:

Nail & Tab in S.E. Face 7" Cherry N. 35° E. 3.51' Nail & Tab in S. Face 18" Hickory EAST 9.80' Nail & Tab in W. Face 6" Cherry S. 05° W. 13.41'

Nail & Tab in S. Face 10" Oak WEST 27.27'

Signed by Surveyor's Michigan License No.

RGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975