	SURVEY &
REM	ONUMENTATION

MAY 1 6 1996

COMMISSION

Surveyor's Michigan License No. 9734

LAND CORNER RECORDATION CERTIFICATE

STATE OF	HICHIGAN
MINTY OF	KALAMAZOO
RECEIVED	FOR RECORD

100 000 00 DM 4 23

IGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

	Carlo Carlo		Eilin	a Doquiron	nant of (1 at 74 B4:	-h DA 4	1070	196	Ubs -	22	PΠ	4 2	3	
For corr Kal	ners in amazoo		Located in:	g Requiren		ner Code #	CN. P.A. 1	1970							
	(County)		Loodica III.		CON	ici Code #			ζ)	ر گزندین پیروس	ich.	مدورس	/	
	lic Land Survey	ζ	Т	R <u>10</u> W. R	****	I-13			Same Times						
in Se	perty Controlling ection cellaneous	s s	T T T T	R R R R							IBER			1477	
Prop	erty in Section	s _	T	. R			L_	Hegi	Register of Deeds Stamp & File Nu						
4. Lot N	No,	. Recorded	Plat						<u> </u>	3 C	D E	F G	нı	JK	
	ate Claims rt E. Snell								2 6		3	9	-310101	-11	
do hereby in lines 1: manual of Managerr 5 above 10 Decree of as expres	y certify that under rand 2 above were in four survey instructionent or by a decree were in conformance a Court of Law; es sed below: Not more than 4 con this certificate.	equirements a conformant ons of the of a Court of the with the a stablished, re- corners, all	of P.A. 74, Note with regular United State of Law and/or rules of the Note that the stablished,	dichigan P.A. cations and rule as Departmen that the corne dichigan Board monumented	of 1970, the es therefore at of the er points m d of Profes d, re-monus	e comer poir as required Interior, Bur- nentioned in assional Surve- mented, reco	its mentione in the currer eau of Lan lines 3, 4 an eyors or by overed, foun	ed nt nd nd a	6 18 7 19 9 10 30 11 12 31	3		21	-22	-23	
A. Des	cription of origina	al monume	ent and acce	essories and	l/or subse	equent rest	oration:		13						
1827:	United Sta							o Sec	tions	34	and :	35.			
	Beech Beech	8" 14"	N. 60 ⁰ I N. 80½0	E. 27 W. 25	7 lks. 5 lks.	, ,						,			
1888:	F. Hodgman in place.	Set pos	st.			, brick	and one	e bear	ring	tree	of r	^e÷si	ırvey	1	
	Maple Maple	4" 4"	S. 22½° S. 67° E	E. 92 E. 136	일 lks. 일 lks.			DV	' KA		ATIF			INTY	
B. Desc	cription of corner	evidence	found and/o	or method a	pplied in	restoring o	r reestablis	זם shing c	dither\√	1ON	UME	ENT	ATIC)N 🖊	
1945:	Wilkins & N	Wheaton	Engineer	ring Co.;	found	tile.			F	PEE	ŖG	RO	UP	44	
	24" Ma Ma 18" E Sign 3	aple aple lm 32nd St.	S. 22½ ⁰ S. 67 ⁰ E North /"T" Ave	E. 5 E. 8 2 e. \$. 80	9.82 89.53 8.10					ź	3/21	196 (/\L	44	
1996:		in monu	ment box	off Nor	thwest	side of West 5.	road. 31'	Pino	ch pi	pe i	n mon	numer	ıt <u>b</u> o	X	
	ription of monun														
I-13:	Southeast of Remonumenta and faithfutile in mon Placed remo	ition Pr il perpe iument b	ogram Pe tuation ox. The	er Group of the p tile wa	on Mai osition s set l	rch 21, n of the nv E. Ho	1996, a e origin doman i	ind is nal co in 188	acce	eptec	l as	a ca	refu		
	PK Nail in PK Nail in PK Nail in Exist. Nail	North S South S /Tab in	ide 3 ide 9 West Si	6" Maple " Pine de Eas		N. 10 ^o S. 66 ^o S. 46 ^o Post	W.	61 90 37	. 24 '). 37 ' '. 77 ' 38 . 42	2 1					
	Who.	15	1	11				1	10	ar.				•	