REMONUMENTATION

MAY 1 6 1996

STATE OF MICHICAN OUNTY OF KALAMAZOO RECEIVED FOR RECORD

of the office to 18 th 18 th 40 th a community of	LAND CORNER I	RECORDATION CERTIF	GATE '96 MAR 1	0 nm .	0 110	
COMMISSION For corners in	Filing Requireme	ent of Act 74, Mich. P.A	. 1970 30 MM L	3 PM :	3 42	
	ocated in:	Corner Code #	\cap			
Pavilion Twp.			Jam	cot You	المستثيد	
·	+ 2 C = 10 M	1 02		-	•	
Public Land Survey	T <u>3 S. R 10 W.</u> T R	J_03	GUDAR	GLERK-REGISTER		
	Ť Ř					
	T R					
	TR		LIBER	1	1452	
	T R T R		ribin	1	TIO	
	_		Register of Deed	s Stamp &	File Number	
4. Lot No, Recorded			A B C	DEFG	ніјк	
5. Private Claims			2 6	5 4 4	_31	
•			3			
•			4-7	·\$\$	_101112	
ı, Robert E. Snell , in a field						
do hereby certify that under requirements in fines 1 and 2 above were in conformant				17-16-1	-151413	
manual of survey instructions of the	United States Department	of the Interior, Bureau of I	Land 7			
Management or by a decree of a Court of above were in conformance with the r			by a	20 21	-22 -23 -24	
Decree of a Court of Law; established, re			ound			
as expressed below:			10 30	29 28	27 26 25	
NOTE: Not more than 4 corners, all on this certificate.	in the same town and rar	nge, may be recorded		32 33	-343536	
on and cordinates			13		ĨĬĨĬĨ	
A. Description of original monume	nt and accessories and/	or subsequent restoration:	•			
1827: Original United St	ates Government S	Survey; set 1/4 Sec	tion post.			
Aspen 10"	N. 56½ E.	192 1ks.				
Aspen 12"	N. 660 W.	980 1ks.				
1888: F. Hodgman, County	Surveyor; found	stake standing at	intersection of	fences	Set post,	
no trees.		•				
	e		- la lita la livra di anno anno			
B. Description of corner evidence	•		_			
1996: Found tile (3" rou fence corner.	nd with "x") on 1	top. The tile is s	set in concrete	at the r	base of a	
rence corner.						
			RATIFIED)		
		BY	KALAMAZOO	COUNT	$\mathbf{Y}(\mathbf{X})$	
		R	REMONUMENT	ATION/	270	
			KALAMAZOO REMONUMENT PEER GRO 2-15-16	UP /		
·			2-15-16	•		
C. Description of monument for co	orner and accessories es	stablished to perpetuate lo	cating the position of	the comer:		
J-03: South 1/4 post Sec	tion 2, T. 3 S.,	R. 10 W., Ratified	d by the Kalamaz	oo Count	ty	
Remonumentation Pr	ogram Peer Group	on February 15, 19	996 and is accep	oted as a	careful	
		osition of the orig				
		te base of fence co 1888 Remonumentatio				
retained as monume		rooo (venominanea (10	n survey. Itle	, HI COM		

15" W. Cherry 15" Oak 12" W. Cherry 3" Oak 16.91' 3.66' PK Nail in East side South Signed by FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 Surveyor's Michigan License No. 9734

PK Nail in West side PK Nail in East side PK Nail in North side N. 10° W. N. 20° W. N. 85° W.

8.37¹ 14.34¹