LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

KALAHAZOO			
(County)	Located In:	Corner Code ≠#	
1. Public Land Survey	T 35 R 11W T 35 R 11W T R T	A-7 A-8	
	TR		
in Section S	T R		
	TR		Register of Deeds Stamp & File Number
. Lot No, Reco	rded Plat	·	A B C D E F G H I J K L A
			2 5 5 3 2 3
			}
GARY C. BILON , in	a field survey onAUGUST	. 19 <u>90</u>	- · 5
o hereby certify that under requirer i lines 1 and 2 above were in con	formance with regulations an	d rules therefore as required to	n tha P 18
arrent manual of survey instruction anagement of by a decree of a Cou	ns of the United States Depar int of Law and/or that the corne	tment of the interior, Bureau of t	Land 7
bove were in conformance with the ourt of Law; established, re-est	rules of the Michigan Board o	III and Surveyors or by a Decree	21 - 22 - 23 - 24 - 24 - 24 - 24 - 24 - 24
rbiassan palow:			d as
OTE: Not more than 4 corner on this certificate.	rs, all in the same town ar	nd range, may be recorded	" ┡┤┼┼┼┼┼┼┼┼┼
:_			12 31 32 33 34 35 36 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
. Description of original monu (A-7) CORNER ESTABLISHED BY	ment and accessories and	/or subsequent restoration:	
(A-B) CORNER NOT SET IN ORIG	LOWS: U.P. NZOW 78.53', 6" INAL SURVEY. FOUND NO REC	OAK S40E 62.62', IRON ROD E ORD OF SURSEQUENT ESTARLISHM	1991) DEC. 1975 AS IRON IN MONUMENT BOX. EAST 33.0'. MENT. CORNER SHOWN ON RECORDED PLATS OF LIBER 33 OF PLATS, PAGE 27).
Description of corner eviden	ce found and/or method a	pplied in restoring or reesta	blishing corner:
(A-7) ORIGINAL CORNER POST AN TO POWER POLE AND RECORDED TH	D ACCESSORIES NOT RECOVERE E TO UTILITY POLE CHECK. G	D. FOUND AND ACCEPTED 1/2° LO FALLING TO STANDARD CORNE	REINFORCING BAR IN MONUMENT BOX. MSHD TIE R CHECKS TO SOUTH.
PREVIOUSLY RECORDED AS A-9 (L)	DEIWEEN A-7 HEKEIN RECORDE CRC LIBER 1. PAGE 4871. TH	D AND A 1/2" REINFORCING BAR E CLOSING CORNER AT A-9 HAS	SECTION 24, T3S-R12N AND NE CORNER SECTION IN A MONUMENT BOX 2.64' NORTH OF A CORNER A CONFUSED HISTORY. SEE LCRC FOR A-9 AND HECKS ACCEPTABLY WITH RECOVERED ORIGINAL
Description of monument for	corner and accessories e	stablished to perpetuate loca	ating the position of the corner:
(A-7) FOUND 1/2" REBAR IN MON SOUTH 24.57' FOUND 1/2" CORNER SEC	NUMENT BOX PREBAR IN MON. BOX AT NE CTION 24, T3S-R12W	(A-8) FOUND 1/2" REB South 48.27' Fo	
RESOURCES T S77E 41.27' SET NAIL AN	ID MICHIGAN DEPT. OF NATURA AG IN W. FACE POWER POLE ID MONR TAG IN N. FACE 18°	NL 532W 82.16' SE' 551E 44.70' SE' OAK NAAW 32.47' SE'	T MAIL AND MONR TAG IN E. FACE 10° CHERRY T MAIL AND MONR TAG IN N. FACE 6" ELM T NAIL AND MONR TAG IN SW FACE 12" QAK
3 104 130.44 SEI MAIL	AND MONR TAG IN E. FACE PO	WEN POLE COLORS	
	PP7 :	GARY C. BILOW	ه د د د
ned by	-10· ·-	大 LAND Atte	2/8/91
rveyor's Michigan License No.	261/53	No.	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1871
M 1		1 10 mm	NEVISEO MAY 14, 1075

PAGE 15