* Lecorded w/error see L. 2 P. 042

COUNTY OF MALAMAZOO RECEIVED FUR RECORD .

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

195 HUG 31	AM	11	35
_			

KALAMAZOO (County)	Located In:	Corner Code #
COOPER TWP.		
Public Land Survey	T <u>3</u> R <u>11</u>	E13
	TR	
	T R	4
	T R	seq./
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Section	S T R	

_, Recorded Plat

4. Lot No.

5. Private Claims _

CLERK-REGISTER

I BER

1 11350

Register of Deeds Stamp & File Number .

, GARY D. HAHN , in a field survey on APRIL 29 , 19 95 ,	
to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned	ı
n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current	t
nanual of survey instructions of the United States Department of the Interior, Bureau of Land	į
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	ì
shows were in conformance with the rules of the Michigan Board of Professional Surveyors or by a	

Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found

as expressed below: NOTE: Not more than 4 comers, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1827 Corner post established by U.S. Deputy Surveyor John Mullett Accessories: Beech 12 in N16°E 311ks. Beech 12 in N56°W 68 1ks.

REMONUMENTATION NOV 06 1998

SURVEY &

SECTION

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Original monument and accessories not recovered.

Found 3/4" dia. 16" long rod in mon. box.

Dug down 4' through dirt and gravel to light sand. Did not find anything. Road is 2' - 3' below natural ground on either side.

> RATIFIED BY KALAMAZOO COUNTY **REMONUMENTATION** PEER GROUP 6-15-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E13, Southeast corner Section 32, T3S, R11W, Ratified by Kalamazoo County Remonumentation Peer Group on June 15, 1995. Location of 3/4" rod is accepted as the best available Strike OF MICHALL evidence of the position of the original corner. Removed rod and replaced with a 30" Harrison Monument in mon. box.

Top bolt on hydrant N1°W 24.89'

Set P.K. nail in W. side of 33" Maple S42°E 35.44"

Set P.K. nail in 16" Maple N46°W 50.45' Set P.K. nail in 18" Maple S50°W 45.37'

Fnd. State of Michigan Monument East 43.50'

Date _8-31-95

Signed by 38116 Surveyor's Michigan License No._ FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

LAND SUR AND S REVISED MAY 14, 1975

AND SURVEYOR

38116