から

AUG 0 6 1996

LIBER

2PAGE 040

_	CONIN	ASSION LAND CORNE	R RECORDATION CERTI	FICATE			
Fc	City of Portage	Filing Requirement of Act 74, Mich. P.A. 1970			× 38.	RE CO	
_	(County)	Located In:	Carner Code #	ر د ا	b g	ECEIV	5 <b>+</b> *
1.	Public Land Survey	T <u>3S.</u> R <u>11W.</u> T R	<u>G-11</u>	CLERK-REGISTE	1 PM	ED F	
	Property Controlling in Section Miscellaneous Property in Section	T R ST R ST R ST R		Register of Dee	ယ် 11 ds Stamp & F	KALAMAZOO Numbe	
		ecorded Plat		А В С	DEFG	ніј	K L
	Private Claims  IWM Job No. 29152		A Map	2 6 3	-5	-32	
do	hereby certify that under requ	in a field survey on <u>May 29</u> direments of P.A. 74, Michigan P.A	of 1970, the comer points ment	tioned 6 18	-17 -16	-1514	13-
ma	nual of survey instructions	informance with regulations and rule of the United States Department of Law and/or that the col	ent of the Interior, Bureau of	Land 7			+
5 a	above were in conformance w	with the rules of the Michigan Bo lished, re-established, monument	ard of Professional Surveyors or	rbya <sub>g</sub>	21 21	-2223	24-
	expressed below:		-2928	-2726	25-		

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

1827 - Robert Clark, Jr., Dep. Surveyor Set post corner to sections 27, 28, 33 & 34 Y. Oak 8 S. 72° E. 26 lks. W. Oak 30 N. 67° W. 102 lks.

1873 - Ed Strong, Stone from U. S.

on this certificate.

1957 - W.D. Ingersoll, RLS, on existing centerline Bacon Road & 3' E. of centerline Westnedge Avenue. P. Pole S. 40° E. 60.40' to tab 24" Catalpa N. 27° E. 40.06' to tab 30" Walnut due West 25.58' to tab. On fence line to West. ±1970 - Sewer construction removed corner (±15' deep)

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

Found 5/8" iron

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
6-20-1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 5/8" iron rod was accepted as the best available evidence of the position of the original corner. Placed Harrison Monument in place of 5/8" iron with mon.box over, Accessories:

Top center of hydrant N. 30° W. 42.07′ 60d nail in 20″ catalpa N. 40° E. 40.08′ "PK" Nail in 12″ Oak S. 45° E. 61.65′ 60d nail in 24″ Walnut West 25.60′

Signed by CM ack.

Surveyor's Michigan License No. 16935

ALLEN H.
MCMACHEN
PROFESSIONAL
SURVEYOR
NO.
16935

8/1/96

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1973

REVISED JAN., 1983