

LAND CORNER RECORDATION CERTIFICATE

For corners in

4. Lot No.

Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY & REMUNUMENTATION

FEB 0 8 2000

SECTION

2 3

4

5

6

8

10

1 10 Register of Deeds Stamp & File Number

Kalamazoo (County)	Located In:	Corner Code#
City of Portage		
Public Land Survey	T <u>3S</u> R <u>11W</u> TR	<u>K7</u>
• •	TR TR	· · · · · · · · · · · · · · · · · · ·
2. Property Controlling in Section	S TR S T R	•••••
3. Miscellaneous Property in Sec.	S TR S T R	

5. Private Claims Gary D. Hahn , in a field survey on <u>July 16</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Recorded Plat

- A. Description of original monument and accessories and/or subsequent restoration:
- 1827 Corner established by U.S. Deputy Surveyor, Robert Clark, Jr. "Set post" Y.Oak 13 N 46° E 18 W. Oak 30 S 78° W 16
- 1864 F. Stimson Co. Surveyor: "Old Gov. stake hole found. Planted stake, stone, pieces of old iron kettle"
- 1883 E. Strong: Gives a distance from the SW. Cor. of Sec. 14 to the SE. Cor. Sec. 14 of 80.71 chains (5326.86 feet)
- 1911 E. Strong "Stone + stake" Hick. 8 S 75° E 67 Apple 8 N 46° E 62

1982 - LCRC L.1, P.837 "Iron in box" 20" Maple N 50° W 75.20 feet 18" Maple N 45° W 53.30 feet SW. Cor. Hse. N 20° E 82.70 feet

KCRC Witness ties:

(W) Conical iron ABT, 12" long (W) Hick. S 65°E 41.2 feet (W) 24" Maple S 30° W 140.8 feet (W) Hick, S 60° W 113.70 feet (W) SW. Cor. Hse. NE. 82.7 feet

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 8-19-1999

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered. Found a 1/2" rebar in mon. box 4' South of centerline of Centre Avenue & 23' East of centerline of Cox's Drive. Found ½" rebar (bent) alongside surface marker rebar 0.8' below road surface. Removed both rebars and found a 4" diameter 3.5' long concrete monument. Top of monument was 1.6° feet below road surface. Monument was 0.05 feet South of surface rebar. Remove monument and dug an 8' x 8' x 5' deep hole through 12" + /- gravel subbase into clean sandy soil. Found no evidence of stake, stone or kettle pieces.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M

K7, Southeast Corner Section 14, Town 3 South, Range 11 West. Ratified by the Kalamazoo County Remonumentation Peer Group on August 19, K7, Southeast Corner Section 14, Town 3 South, Range TT vvest. Natined by the relatinazou country remonumentation Teel Group of Cognition of the concrete monument is accepted as the best available evidence of the position of the original corner. Replace concrete monument with a 30" Harrison monument in a monument box.

Witness Ties:

Set Mag nail in P.P. N 60 ° E 53.27 feet
Found nail w/tab in P.P. S 5 ° E 57.03 feet

Set Mag nail in 22" Maple N 41° W 53.34 feet Set Mag nail in Apple N 13° E 43.79 feet

38116

Signed by Surveyor's Michigan License M

10/18/99

Date

38116

LAND SURVEYORS, FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN.28,1971

REVISED MAY 14.1975

REVISED JAN., 1983 REVISED OCT., 1995

HALW

LAND SURVEYOR