SEP 1 1 1996

COMMISSIDAND	CORNER RECORDATION CERTIFICATE
=	Demoissment of Act 74 Mich D'A 1070

2	COM		ER RECORDATION CERTI	IFICATE	と言語
		Filing Requir	ement of Act 74, Mich. P.,	A. 1970 CLERK	Till and an
For corners in Kalamazoo		Located in:	Corner Code #	₹.	0F 70 0F 70 23
Portage Ti				REG	R PA
1. Public Land S	Survey	T3 <u>S.</u> R <u>11 W</u> TR		ISTER	1 1 1 1 2 2 3
Property Con	etrollina S	T R T R T B	Jea. #2	LIBER	1 PAGE 1500
in Section	S	TR	pm		21700,2000
3. Miscellaneou Property in S		T R T R		Register of Deed	ls Stamp & File Number
4. Lot No	, Recor	ded Plat		A B C	DEFGHIJKE
				f 1 '' 1	

I, Robert E. Snell , in a field survey on _____April 3 _____, 19 96 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Sequence # 1 is Liber 1 Pg 1350

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyors; set post, corner to Sections 32 & 33.

Wh. Oak 14"

N. 01⁰ E. N. 42⁰ W.

320 1ks.

Wh. Oak 7"

F. Hodgman, County Surveyor; found stake in marsh, 80 lks. East of corner to Sections 1889: 32 & 33. (In remonumentation survey for Schoolcraft corners to Sections 4 & 5).

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

Found rusted 3/8" iron in timber in swamp. Further digging revealed wooden stake 1.7' East of iron, top rotted off, old fence post rotted off was found to the North of wood stake. United States Government called for 80 lks. jog. F. Hodgman called for 80 lks. jog, it measured 52.34' from stake to tile set by F. Hodgman, County Surveyor. 3/8" iron is believed to have been used in survey for "Sugarloaf Acres Plat" by Gove recorded in L-22 , P-22 of plats.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 4-18-1996

86 BE 81

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Southeast corner Section 32, T. 3 S., R. 11 W., Ratified by Kalamazoo County Remonumentation Program Peer Group on April 18, 1996 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found wood stake 52.34' West of 3" round tile set by F. Hodgman in 1889 Remonumentation survey for Schoolcraft Township. Wood stake is believed to be Government stake set in 1825. Removed wood stake and placed 30" Harrison Monument in its place.

•		•	
PK Nail in West Side	18" Maple	S. 10° W. S. 60° W.	51.73'
PK Nail in Northwest Side	Triple 7" Maple	S. 60° ₩.	38.721
PK Nail in South Side	12" Maple	N. 50° W.	36.63'
PK Nail in North Side	6" Poplar	S. 44 ^D E.	39.91'

Surveyor's Michigan License No.