

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

G-5 KALAMAZOO COUNTY


T 3.S. R 12.W.

DESCRIPTION OF CORNER N. W. COR. SEC. 15

CORNER MONUMENT DRILLED STONE

DATE MONUMENT ~~PLACED AND~~ WITNESSED 9-18-70

WITNESSES TO CORNER..... S. 69° W. 37.7 W. PINE



WEST 39.6 18" BEECH

N. 15° W. 74.0 18" OAK

AND
N. 37°-30' E. 61.0 12" WALNUT

CIRCLE CORNER REGISTERED S. 44° E. 41.5' 24 WALNUT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

*This corner was recovered using notes received from
Engineering and Surveying of Kalamazoo, Michigan*

SURVEYOR'S SEAL

SIGNED _____ DATE _____

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68