

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

G-6 Kalamazoo COUNTY

T 3S. R 12W.


16

DESCRIPTION OF CORNER W. 1/4 COR. SEC 15

CORNER MONUMENT 1/2" Iron Rod

DATE MONUMENT ~~PLACED~~ WITNESSED 9-18-70

WITNESSES TO CORNER..... N. 27° W. 77.2' Power Pole



N. 32° E. 42.0' 36" Oak

S. 35° E. 29.9' Power Pole

AND
S. 10° W. 30.5' N.E. Corner Bldg.

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

*This corner was recovered using notes received from
Geo Engineering and Surveying of Kalamazoo, Michigan*

MRLO

SURVEYOR'S SEAL

DISTRIBUTION: SIGNED _____ DATE _____
REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68