			NER RECORDATION			(1.	730 86.	COL RE
Fo	r corners in KALAMAZOO	TWP Filing Requ	irement of Act 74, N		CLERK	M		
	KALAMAZOU (County)	Located In:	Corner Code	#	泛			NE TE
					1 .		22	ED F
1.	Public Land Survey	T <u>3S.</u> R <u>12V</u>	V . <u>J-5</u>		NE Y	1.3	-0	KALAMAZOO FOR RECORD
		T R		2PAGE	<u>a</u>	3	3	255
		T R				6 %	1	一四五百
2.	Property Controlling	T R S T R		رنت ا	. 50	Ž	22	70 유
	in Section	S T R			•	. *******	1 🕠	00
3.	Miscellaneous	S T R	<u></u>			_		
	Property in Section	S T R		Registe	r of Deeds	s Stamp	& File	Number
4.	Lot No	ecorded Plat						
5.	Private Claims				A B C	D E F	G H	1 J K
				2		}─ ╅─		
b.	IWM Job No. 24130			3			++	
1.	Allen H. McMachen	in a field survey on _Septen	nher	. 19 98 5		} 	10	11-1-
do	hereby certify that under requ	irements of P.A. 74, Michigan I	P.A. of 1970, the corner po	oints mentioned	18-1-1			191
in l	ines 1 and 2 above were in co	nformance with regulations and	d rules therefore as require	ed in the current	lïli	7-1-16-	15.	14-1-
		of the United States Depar a Court of Law and/or that the		ureau of Land	19-1-2	021-	-22-	23
5 a	bove were in conformance w	vith the rules of the Michigan lished, re-established, monume	Board of Professional Su	rveyors or by a			$\perp \bar{\downarrow}$	
	expressed below:	iisned, re-established, monum	anteu, re-monumentea, re	ecoverea, touna 10	302	9	27-	-26
NC	NOTE: Not more than 4 corners, all in the same town and range, may be recorded			ded 11			+	- - -
	on this certificate.			12	31 -3	2——33~	34-	35
A.	Description of original m	nonument and accessories	and/or subsequent re	storation:	<u> </u>			
	1921 - A. Lenderink, Sur 1940 - A. Lenderink, Sur 1960 - W.D. Ingersoll, R. and South tab West; N.	Set quarter Section post, E rvey of Boy Scout proper rvey shows North quarte .L.S., Reset corner per 192 45° W. 52.51 feet to 30" V et to Northwest corner bi	ty shows North quar r corner. A.S. LEO.S 21 & 1940 Lenderink Vh. Oak tab South sid	Surveys. S. 10° E. 36' le; N. 20° E. 36.92 fee	to P.P. lin	es Norti . Oak tal	b	
В.		idence found and/or metho				al		
	or control.							
		SURVEY &						
	REN	MONUMENTATION		R	ATIFIE	D		11
	NOV 2 5 1998			BY KALAN REMON	MEN	COL	TINITY	r V
		SECTION		ree (RATIFIE BY KALAMAZOC REMONUMEN PEER GRO			•
C.	Description of monumen	nt for corner and accessorie	es established to perp	etuate locating the po	sition galt	_{el} HHHHHH ie c órn <i>é</i> l	MANAGE 1:1 C N	************************************
	Position of found iron rod is accepted as the best available evidence of the position original corner. Replaced found iron rod with a 20" Harrison Monument, Accessed NW corner concrete foundation (Health Bldg.) S. 84° E. 47.18′ Nail in North side of 18" Oak N. 76° E. 35.80′ Nail in SE side of 18" Oak S. 89° W. 12.3′ Nail in West side of P. Pole S. 05° E. 35.90′ Iron rod S. 45° W. 3′				Man 1	ALLEN McMACH	I EN	72
	NW corner concrete Nail in North side of Nail in SE side of 18 Nail in West side of Iron rod S. 45° W. 3' Iron rod S. 45° E. 3'	foundation (Health Bldg.) S. 84 f 18" Oak N. 76° E. 35.80′ " Oak S. 89° W. 12.3′ P. Pole S. 05° E. 35.90′	₽° E. 47.18′		LICENSED MANAGEMENT	PROFESSIO SURVEYO No. 16935 OR OFES SIO	OR ONAL	Sold Market

Signed by

Surveyor's Michigan License No.

PORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN... 1983