SURVEY & REMONUMENTATION

2PAGE 102 JUL 2,3 1997 LIBER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Kalamazoo Located In: Corner Code # 1. Public Land Survey Т 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section 4. Lot No. _, Recorded Plat_ 5. Private Claims IWM Job No. 28528 Allen H. McMachen , in a field survey on May 9 96 . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

- 1826 Robert Clark, Jr., Intersected West Boundary 7 lks. North of (phrase ends). Set post at intersection. Corner to Sections 19 & 30. W. Oak 12" S. 56° E. 59 lks., W. Oak 16" N. 21° E. 75 lks.
- S. Hodgman, D.C.S., "Section corner established from the Northeast quarter of Section 25, Schoolcraft 1869 which was set from the stumps of two witnesses. Stone corners are set for both. "A" (NW cor., Sec. 30) is 7 lks. North of the corner of Section 25.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron rod in monument box. Removed iron and box and excavated. Found pointed stone 2' below grade. Stone was 0.2' South and 0.7' West of iron location.

> RATIFIED BY KALAMAZOO COUNT REMONUMENTATION PEER GROUP 6/20/1996 (

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found pointed stone was accepted as a careful and faithful perpetuation of the position of the original corner. Placed Harrision Monument over stone and monument box, Accessories:

S.W. corner of House N. 60° E. 170.29' N.W. corner of Church S. 45° E. 287.12' Nail & Tab in 12" B. Walnut S. 70° W. 84.21' Nail & Tab in 18" Sassafras N. 65° W. 55.84'

MICHICA ALLEN H. McMACHEN PROFESSIONAL. SURVEYOR No. 16935

Signed by

Surveyor's Michigan License No.

PROFESSIONA

NOVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14 1975