SURVEY & REMONUMENTATION

LIBER 1 PG1195

APR 2 7 1995

on this certificate.

COMM For corners in	1221011	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970			STATE	
Kalamazoo	Located In:	Corner Code ##	CLERK	မ	E O	
Brady Township			r 🤼		- F - F - F - F - F - F - F - F - F - F	
Public Land Survey	T 4 S R 10 W	<u>D-12</u>	REGIS	AM	□ ≥ =	
	T R		TS .	9		
			TER	<u> </u>	SAZ AZ	
2. Property Controlling	S T R		•	24	AMAZOO RECORD	
in Section	S T R					
Miscellaneous	S T R		Register of Deeds	Stamp &	File Numl	\ar
Property in Sec.	S T R		Tregister of Deeds	————		
4. Lot No , i	Recorded Plat		· · · · · · · · · · · · · · · · · · ·			K 1 1
5. Private Claims			îir	EFG	HIJ	
			2 6 5 -	╌┼╌ᢤ╌┼╴	- 3 2 -	 - -
			3	-+-+-		++-
. Robert F Snell	, in a field survey onJune	. 6 01	4 - 7 - 8-	┼╬┼	-10-+-11-	-12-
	quirements of P.A. 74, Michigan P.A. o		nned	++-	+++	 -
in lines 1 and 2 above were i	in conformance with regulations and	I rules therefore as required in	the 18 17	16-+	1514	- 3
current manual of survey instr	ructions of the United States Departr	ment of the Interior, Bureau of L	Land 7	+-+-+	+++	++-
	a Court of Law and/or that the corner ith the rules of the Michigan Board of				_2223_	24
	re-established, monumented, re-m			- - - 	- - - 	++-
expressed below:			10 30 29	28	_2726_	

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

1919: Kalamazoo County Road Commission; Field notes and plans show stone for Center of Section 32.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found PK Nail below surface of pavement. Further digging produced a railroad spike and a stone (18" x 18" x 12") with a drill mark, 8" below the surface.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
9-16-14

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-12 Center of Section 32, T. 4 S., R. 10 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on September 15, 1994. Found drilled stone as called for in Kalamazoo County Road Commission field note and plans from survey in 1919. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner. Removed PK Nail and Railroad spike, lowered stone and placed a 20" Harrison Monument over stone and a monument box over.

-	PK Nail in	Southeast	Side 34"	0ak N 50°	° E 57.50'	fir.;	Charter Ti	3 1/1
	PK Nail in	Northeast	Side 30"	Maple S 5	58° E 51.22'			
	PK Nail in	Northwest	Side 45"	Walnut S	64° W 52.20'	in CL	of 27th to	North
	Notch in To	op 6" Steel	l Post Fil	led with	Concrete N 28°	W 45.52' CL	of "Y" Ave	S 2.6
	Notch in T	op 6" Stee	l Post Fil	lled with	Concrete N 54°	W 44.72'	- 4 /	
	De	1.00	Full	//	Data	12-	9-94	

Surveyor's Michigan License No. 9734 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983