

**SURVEY &
REMONUMENTATION**

APR 27 1995

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

<u>Kalamazoo</u> <small>(County)</small>	Located In:	Corner Code #
<u>Brady Township</u>	T <u>4</u> S R <u>10</u> W	<u>E-1</u>
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

CLERK - REGISTER

94 DEC 30 AM 9 18

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

1 PG 1236

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on June 2, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Enter North Boundary at Post.
Wh. Oak 9" North 76° East 20 Lks
Wh. Oak 9" North 86° West 12 Lks

1888: F. Hodgman, County Surveyor; Found old stake packed around with stones. Set Post.
W. Oak 18" South 45° West 46 Lks
Hickory 8" South 09° West 47 Lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found PK Nail in Road, 1.0' South of Center Line and 33' North of broken plat monument. Three (3) feet below surface, found 3" round tile about 0.4' South of position of PK nail.

NOTE: This Corner is a corner in common with Southeast Corner Section 32 (E-13) Pavilion Township.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
7-21-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1 Northwest Corner of Section 4, T. 4 S., R. 10 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 21, 1994. Found 3" tile as placed in 1888 remonumentation survey by F. Hodgman and is accepted as a careful and faithful perpetuation of the position of the original corner. Placed a 20" Harrison monument with a monument box over.

PK Nail in West Side	Power Pole	North 18° East	33.07'
Northwest Corner of Top Brick on	15" Sq. W. Drive Piller	North 52° East	72.26'
PK Nail in Northeast Side	12" Poplar	South 50° East	45.34'
PK Nail in East Side	20" Poplar	South 24° West	44.76'
Center Line "T" Avenue		North	1.00'

Signed by Robert E. Snell Date 12/28/94
Surveyor's Michigan License No. 9734

