in the second

## COMMISSION LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in	Filing Req	uirement of Act 74, Mich. P./	<b>a. 1970</b>
_	KALAMAZOO (County)	Located In:	Corner Code #	
	BRADY TWP.			Jening
1.	Public Land Survey	T <u>4</u> R T R T R		CLERK-REGISTER
_		. T R		LIBER 1 1344
2.	Property Controlling in Section	S T R S T R		LIBER I MIOHH
3.	Miscellaneous	S T R		
	Property in Section	S T R		Register of Deeds Stamp & File Number
4.	Lot No	, Recorded Plat		ABCDEFGHIJKL
5.	Private Claims			

GARY D. HAHN, in a field survey on \_\_APRIL 29, ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

HAHN AND SURVEYOR

No

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post established by U.S. Deputy Surveyor Robert Clark, Jr., 1826. Accessories: Beech 16 S57°W 21 lks.

Beech 15 S73°E 73 lks. BURNESS OF MICKING

1872 S. Hodgman - Found Stake. Correct by 2" stump beds. Noted without marking. Accessories: Sugar 3" N23 1/2 E 104 1/2 lks. Blk. Walnut 3" N24 1/2 W 104 lks.

KCRC notes call for stone - no accessories - no date.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

LAND SURVE LAND SURVE Original corner with accessories not recovered. Fnd. 1/2" dia. rebar 24" long in mon. box buried 6" below asphalt road. Removed rebar and fnd. 9"x13"x18" stone with point up 20" deep. The west flat side of the stone and its point were butting against the east side of the rebar. Stone and rebar were virtually in same location. Held rebar for witness ties.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION

PER GROUP
6-15-96
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K6, E1/4 Corner Section 14, T4S, R10W, Ratified by Kalamazoo County Remonumentation Peer Group on June 15, 1995. Found 1/2" rebar 24" long in mon.

box and along side a 9"x13"x18" pointed stone. 1/2" rebar is accepted as the best available evidence of the position of the original corner. Removed rebar and stone and set 30" Harrison monument in mon. box. Accessories: Fnd. 1/2" rebar west 33.03'

Set P.K. Nail in 18" Oak S70°E 62.59' Set P.K. Nail in 11" Twin Oak N75°E 80.05' Set P.K. Nail in 22" Oak N77°W 30.29'

Date <u>AUGUST 18</u>, 1995 **3**8116 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971