FEB 1 8 1994

LIBER 1 PG 103

STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE 93 NOU 18 PM 3 46 Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	· · · · · · · · · · · · · · · · · · ·			<i>(</i> -"	Š	-						
	Kalamazoo (County)	Located In:	Corner Code ##			Las	بدير	974	TER	_			
	Brady Township		·			CLE	RK-	REGIS	TER				
1.	Public Land Survey	T <u>4 S</u> R <u>10 W</u>	T 4 S R 10 W L-7			0							
	Α.	T R	·						•				
		T R	·										
		T R											
2.	Property Controlling	S T R											
	in Section	S T R	·										
3.	Miscellaneous	S T R		Pagi	ictor	of D	oode !	Stame	& File	. No.	sho-		
	Property in Sec.	S T R		11,091	12561			otomp		; recent	ivei		
			•	•					-				•
4.	Lot No Re	ecorded Plat							· · ·		ب		
					â	T 1		1	1	 	- 	_ M	ŀ
-			•		2	- 6	5 -	╂∳-	- 	- 2	+	- -	İ
		· ,	•		3 <u> </u>			┦	+	\dashv	-		ı
					4		_ l_	 -9-	10		4	_	ı
į	John G. Kester	in a field survey on Al	ugust 17 . 19 93		5	<u>i</u> l	Ĺ.		ΔĨ			Ĩ.	ļ
			of 1970, the corner points mention		٦								ı
		-	nd rules therefore as required in		٦	-18	-1/-	1 16-	† "	1-14	'-	-13 	į
		· · · · · · · · · · · · · · · · · · ·	rtment of the Interior, Bureau of L	,	. ′⊢	+-		1	1-+	1-1	\dashv	•	ļ
			er points mentioned in lines 3, 4 a of Land Surveyors or by a Decreë		8	19	-20-	21-	22-	2'3	, 	-24-	i
aυι Co	ove were in conformance with out of law established re	established monumented re-	monumented, recovered, found	d as	⋼┝	+			╂┷┼		-+-		ł
	pressed below:	ootabiionoo, ijidaabiioonoo, id			10	-30	29	28-	27-	26	<u>. </u>	_25	ł
		rners, all in the same town a	and range may be recorded		11				\perp				l
110	on this certificate.	mers, an in the same town a	me tange, may be toot acc		12						.	20	ļ
	On this Certificate.				.,[-31		7-33-	7-3	7,	<u></u>	30	İ
A.	Corner Post est		nd/or subsequent restoration: vernment Deputy Sur h 18 N81W 14.		Rob	ert	Cla	rk,]	L826,)		•	•

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner and accessories not recovered.

and marked large Stone >+> S54W 35 Lks.

Found 1/2" Iron in Monument Box above Cone shaped Stone with Drill Hole believed to be Stone called for by Ed Strong Survey in 1872. Accessories not recovered.

Survey by Ed Strong, County Surveyor, 1872, Bisected 3-4 Set Stone with Lead center

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
9-16-93

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-7, S\(^1\) Corner Section 13, T4S-R1OW, Ratified by Kalamazoo County Remonumentation Program Peer Group on September 16, 1993. Found \(^1\) Iron in Monument Box above Cone shaped Stone with drill hole (Removed \(^1\) Iron and Monument Box. Placed 20" Harrison Monument above Cone shaped Stone with drill hole and placed Monument Box over Corner) and is accepted as a careful and faithful perpetuation of the position of the original Corner.

Set 6" Spike in 10" Box Elder S15W 48.96' Set 6" Spike in 9" Box Elder N15W 34.25'

Set 12" Rebar S50E 42.44'

Center of South End 40" CMP S10W 31.43'

Signed by July The S	Date	11-17-93		
Surveyor's Michigan License No. 16046		FORM APPROVED BY MICHIGAN	STATE BOARD OF LAND SURVEYORS, JAN. 28	, 197

Kalamazoo County Road Commission

REVISED MAY 14, 1976