

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Kalamazoo (County)	Located In:	Corner Code#								
Brady Twp. 1. Public Land Survey 2. Property Controlling in Section S 3. Miscellaneous S Property in Sec. S	T_4S R 10W T R R T R R T R T R T R T R T R T R T R	M4								
4. Lot No, Recorded Plat										
on this certificate.										

SURVEY &
REMONUMENTATION

FEB 0 8 2000

SECTION

Register of Deeds Stamp & File Number

1 A	В	C	D	E	F	G	Н	Ι	Ĵ	K	L	M
2 —	- 6-		-5-		 -4-	_	-3-		-2-	.	- 1-	_
3 –	+	-			+	_ -	+	-	_	-	_	_
4	-7-	-	- [8—	1	- 9		-1 0-		-1,1-		-12	•
5		+	+	+-	+			1	+	+	+	\dashv
6 -	1/8-		-17-	-	-1,6-	+	-15-	+	-1 4-	-	-13	\dashv
7		+	1		+	+	1	+	+	+	+	\dashv
.8	-1 [*] 9		2'0 		-21- 	1	22 	1	-23- 	\dagger	-24- 	7
9 —				-	\top	1	_	_	\top	1	+	
10	3¦0-		-2 9		-2 8-	-	-2 ['] 7-	+	-2 [¦] 6-	╁	-2 ¹ 5-	_
11-	+			+-	+	+	+	+	+	+-	+	\dashv
12-	–3 ['] 1– 		3 ['] 2	+	-3'3- 	\dagger	–3'4– ∣	+	-3 ['] 5-	-	-3 ₆	\dashv
13												

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1826 - Corner established by U.S. Deputy Surveyor Robert Clark, Jr.: "Set 1/4 sec. post in Indian

1905 - E. Strong Co. Sur.: "Lost. Set drilled stone Cherry 6 East .50 Elm 18 N 89 ° W .57"

A. Description of original monument and accessories and/or subsequent restoration:

W. Oak 18 S 15° W 69 L. W.Oak 10 N 45° W 41 L.

Original monument and accessories not recovered. Found a 1/2" diameter 18" long rebar in a 2" diameter 3" long pipe in asphalt road. Measured 105.49 feet to a 1/4" rod at Wakeshma corner A-4. Found a 10" x 13" x 18" stone with point lying on its side pointing north. Straightened stone and found a drill hole on the point. Stone was in gravely sand about 2.5 feet below road surface just under old road bed. The position of the straightened stone was 0.61 feet North and 0.51 feet West of the surface marker. Removed the stone to excavated a 5' x 5' x 5' deep hole. No other evidence found. Reset the stone at a distance of 105.49' North of a 1" diameter pipe found below the road surface at the Wakeshma corner and at the same easting as the ½" rebar surface marker. Stone is at a depth of 19" below road surface. It was the decision of the Kalamazoo County Remonumentation Peer Group to reestablish this corner at the bisection of Brady Township corners M-3 and M-5.

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner;

M4, East Quarter Post Section 12, Town 4 South, Range 10 West. Ratified by the Kalamazoo County Remonumentation Peer Group on September 23, 1999. The location of the bisection of the line made up by Brady Township corners M-3 & M-5 is accepted as a careful and faithful reestablished of the position of the corner. Set a 20" Harrison Monument in a monument box at said bisection.

Witness Ties:

For corners in

Found Pk nail in 18" Ash N 54 ° E 38.09' Found PK nail in 12" Ash S 58 ° E 35.82' Found nail w/tab 10" Ash S 40° W 40.42' Found nail w/tab in fence post \$ 80 ° W 32.21'

HATIFIED BY KALAMAZOO COUNTY REMONUMENTATION

PEER GROUP/ 9-23-1999

GAR.
HAHIN
NO.
38116

SSIONAL SURVEYOR
JAN28, 19975
VISED OCT

10/18/99 Date

Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,