## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY 27	т. <u>4</u> <del>s.</del> , R. <u>И</u> <del>w</del> .	I-9	
2. PROPERTY CONTROLL- ING IN SECTION-	,T N. R E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 12————————————————————————————————————			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Found 3" fire clay cylinder with cross in frace line 4" below ground.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  3" fire clay cylinder with cross in fine line 4" below			
ground.			
5 17°E, 49.2	28', 13" Hickory	Pk & tog.	
365°€, 26.	25', 14" Ook, P	k & tog.	
N50° €, 23.3	s', 24' Oak, p	K & tog.	
SIGNED BY	•	DATE	
SURVEYOR'S MICHIGAN REC	ISTRATION NO		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY.	Donald Townstered LA	DATE	/2-10-74 (SEAL)