

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	nazoo	Located in:	Corner Code#				i	end.	\/ = \	√ <i>R</i> .				
(County) This corner common to SE corner Sec. 25, Prairie Ronde						REMONUMENTATION								
1. Public Land Survey						FEB 0 8 2000								
TR						SECTION								
3. Misc	ection S cellaneous S perty in Sec. S	TR TR	-		Re	giste	er of Do	eeds S	tamp	. & F	ile N	lumb	er	
4. Lot I	No, Recorded P	lat			A E	, ,	n 1		c u	, т	.7	ĸ	L	
J. 1 11V	aro oranno				2 2		-5-		G H			Ť	Ţ-	
					3			\vdash			+	- -	+	
i, Robert E. Snell , in a field survey on Oct, 16 ,19.99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					4	1	— 8— 	9 	1		11- 	\neg	-12- 	
United Sta	ates Department of the Interior	r, Bureau of Land Manac	the current manual of survey ins gement or by a decree of a Cour	t of Law and/or	5 1	a	_17_	_16_		5	14		-13-	
Board of I			e in conformance with the rules of blished, re-established, monumer		7				\perp	\vdash		-	- -	
NOTE:	•	all in the same town a	and range, may be recorded		8 -1	9	20 	2 1	1-2	2	23- 	-	-2 '4	
	on this certificate.				9		_				十	\top	+	
					10 3		29	28		П	-26- 		-25-	
_				•	12—3	1	 3 <u>2</u>	33_	3	4	 —35-		-36-	
A. Des	scription of original mo	nument and access	ories and/or subsequent r	estoration:	13							_1_		
1825:	United States Governr	nent Surveyors, R.	Clark; set post, ralsed mou	und in prairie.										
1826:	United States Governr	nent Surveyors, R.	Clark; entered W. boundar	y at post (mount in	prairie).								
1869:	F. Hodgman, County S	Surveyor; a stone is	set in the fence on the pra	irie.										
1872:	S. Hodgman, County 8	Surveyor; stone in c	orner of fence.											
1889:	F. Hodgman, County Surveyor; found stone for corner at end of picket and wire fence and in line with willow hedge running North. Set post with stone beside.													
B. De	scription of corner evi	dence found and/c	or method applied in rest	oring or reestablis	hing c	orn	er:							
1940:	Wilkins & Wheaton Engr. Co.; found stone in fence corner with tile 0.5' South of stone. No witnesses.													
1972:	Wilkins & Wheaton Engr. Co.; found tile in E & W fence line 6.5' East of fence to North.													
1999:	9: Found tile 22" below surface in farm field. Top section and 8" of bottom 2 ft. section have been damaged, lower section was good. NOTE: All fences gone.													
			_											
C. De	scription of monument	t for corner and ac	cessories established to	perpetuate locati	ng the	pos	ition o	of the o	corne	er:				
A-11:	November 18, 1999 ar F. Hodgman, County S	nd is accepted as a Surveyor in 1889 Re	11 W., ratified by the Kalar careful and faithful perpetu emonumentation survey. R irons at 4 cardinal compas	lation of the position Removed tile and pla	n of the aced 2	e orig 2" of	ginal co Harris	orner. on mo	Four	nd tile ent ir	e as ı its ı	set l	by e,	
	Tile Sleeve (Northwest Tile Sleeve (Southwes Bound in center line of Harrison Monument So	t corner Section 31, Route U.S. 131 So	, Schoolcraft)	Assumed North S. 0°-07'-00" W S. 87°-43'-16" I N. 89°-37'-18" \	<i>I</i> . E.		5,315 5,323 2,368 5,303	3.79' 3.94'						
Signed	by John to	3 Luc	4	Date//	- Z	Z	-99	3						
Surveyo	or's Michigan License No	o. <u>9734</u>	′	•										
	P3 A =	Time o												

BY KALAMAZOO COUNT REMONUMENTATION PEER GROUP