SUNVEY &
BEMONUMENTATION
7- "SINDMENTATION
á


DV AUC DA MOO

•	- HOU 0 6 1	396 LAND CORNER I	RECORDATION CERTIFIC	
	45 65 to 0 to 10 to	Filing Requireme	ent of Act 74, Mich. P.A. 1	1970
or corners in Kalamaz	OOMMIS	Filing Requirements SION Located In:	Corner Code #	2 6 3 9 5 5
School	craft Twp.			Y 0 VEL 22
I. Public La	nd Survey	т4 <u>S.</u> <u>R</u> <u>11 W</u> .	E-01	TO SE
		T R		R RE
		T R		ER 1 EO
	Controlling S	5 T R		THE STOCK ORD
in Section		S T R		LIBER 2PAGE 013
3. Miscellan		3T R		Register of Deeds Stamp & File Number
Property	in Section S	5 I K		negister of peeds stamp a rile number

____, Recorded Plat___ 4. Lot No. 5. Private Claims ___

I. Robert E. Snell, in a field survey on April 3 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1826: United States Government Surveyors; enter North Loundary 80 1ks. East of post. Set post at intersection of corners 4 & 5.

Tam 8"

S. 63⁰ E. S. 81⁰ E.

359 1ks.

329 1ks.

F. Hodgman, County Surveyor; found stake in marsh, 80 lks. East of corner of Sections 32 & 33. Set post. 1889:

W. Oak 20"

N. 54½° W.

234 1ks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found tile 1' long 3" round laying on its side above second section of tile in good position. Placed top section over good tile measured 52.34' from tile to U.S. Government corner post, as found Government and Hodgman measured 52.80'.

RATIFIED BY KALAMAZOO COUNTY, REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Northeast corner Section 4, T. 4 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on April 18, 1996 and is accepted as a careful and faithful perpetuation of ths position of the original corner. Found 3" round tile as described in "B" above, tile was set by F. Hodgman in 1889 remonumentation survey. Placed remonumentation sleeve over tile.

Center of	20" Harrison Mon.	West _	52.341
PK Nail in West Side	6" W. Cherry	N. 02 ⁰ E.	22.20'
PK Nail in North Side	5" W. Cherry	N. 58 ⁰ W.	24.451
PK Nail in North Side	16" Tamarack	s. 78 ⁰ E.	49.15'

Surveyor's Michigan License No.