SURVEY & REMONUMENTATION

| STATE OF | HICHIGAN |
|-----------|------------|
| COUNTY OF | KALAMAZOO |
| RECEIVED | FOR RECORD |

APR 2 7 1995

LAND CORNER RECORDATION CERTIFICATE, 94 DEC 14 PM 2 39 Filing Requirement of Act 74, Mich. P.A. 1970

| For | r corners in COMM | ISSION Filing | Requirement of Act 74, Mich | n. P.A. 1970 31 DEC 11 111 E 33 |
|-----|----------------------|-----------------------|-----------------------------|---------------------------------------|
| | alamazoo | Located In: | Corner Code ## | James Jours |
| | Choolcraft Townsh | | | CLERK-REGISTER |
| 1. | Public Land Survey | т <u>4 S</u> R т R | | OLEM MEGIOTEM |
| | | T R | ····· | 4 1910 |
| 2. | Property Controlling | T R S T R | | LIBER 1 PG1210 |
| | in Section | S T R | | |
| 3. | Miscellaneous | S T R | | Register of Deeds Stamp & File Number |
| | Property in Sec. | S T R | | |
| 4. | Lot No , F | Recorded Plat | | ARCDEFGHIJKI |
| 5. | Private Claims | | | · · · · · · · · · · · · · · · · · · · |

Robert E. Snell, in a field survey on May 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Set 1/4 Section Post.

11" Y. Oak South 39 %° 38 Lks East 82° Y. Oak 14" 23 Lks South West

1889: F. Hodgman, County Surveyor; Found stone said by Theron Adams to have been kept in place for more than twenty years for the Corner. No bearing trees left and no other evidence of Corner. Set Post.

> 12" Hickory South West 172 Lks 12" Hickory South 09° East 190 Lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 24" iron rod at surface. Found tile 3' below surface, next to a notched stone.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 Post Section 26, T. 4 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 21, 1994. Found tile as called for in 1889 remonumentation survey by F.Hodgman and is accepted as a careful and faithful perpetuation of the position of the original corner. Left tile and stone in place and placed a 20" Harrison monument and monument box at the surface.

| CL | "Y" Avenue | In Line | | |
|----|--------------------|----------------|----------------|--------|
| PΚ | Nail in South Side | 36" Maple | North 55° East | 39.60' |
| PK | Nail in West Side | Power Pole | South 30° East | 87.45 |
| PK | Nail in South Side | Telephone Pole | South 72° West | 82.31' |
| PK | Nail in North Side | Telephone Pole | North 32° West | 42.72 |
| CL | 21st Street | 1 | East | 1.5' |

Tel 2. trulf Date 12. 14. 94